



<b>Countries:</b>	AUSTRALIA, BRAZIL, CANADA, TAIWAN, UNITED STATES, MEXICO, GUAM, KOREA, SOUTH KOREA, SOUTH AFRICA	<b>Document ID:</b>	IK0300008
<b>Availability:</b>	ISIS, Bus ISIS, FleetISIS	<b>Revision:</b>	9
<b>Major System:</b>	SPRINGS AND SUSPENSION	<b>Created:</b>	4/25/2007
<b>Current Language:</b>	English	<b>Last Modified:</b>	11/18/2015
<b>Other Languages:</b>	NONE	<b>Author:</b>	David Horner
<b>Viewed:</b>	6009		

[Less Info](#)

Hide Details

Coding Information

<b>Copy Link</b> 	<b>Copy Relative Link</b> 	<b>Bookmark</b>  <a href="#">View My Bookmarks</a>	<b>Add to Favorites</b> 	<b>Print</b> 	<b>Provide Feedback</b> 	<b>Helpful</b>  733	<b>Not Helpful</b>  1569
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	---------------------------	--------------------------------

**Title:** Vibration Troubleshooting

**Applies To:** All International Trucks

### Change Log

**Dealers:** Please refer to the change log text box below for recent changes to this article:


<p>11/18/2015 - Repaired hyperlink to Mekra Lang manuals. Re-formatted article layout.</p> <p>11/02/2015 - Added info from IK0100013 &amp; IK1200666</p> <p>10/16/2015 - Removed content about discontinued tool - ZTSE 4580 and updated Author for feedback purposes</p> <p>04/01/2015 - Added Frequency Graph</p> <p>08/28/2014 - Deleted the yellow highlighted links that were not really links.</p> <p>08/05/2014 - Author updated for feedback purposes</p>
---

### Description

- This article will cover the following information on vibrations:
  - Vibration troubleshooting flowchart.
  - Vibrations caused by engine mounts.
  - Vibrations caused by cab mounts.
  - Correcting mirror shake not caused by engine or cab mount issues.
- For vibrations caused by driveline issues please refer to [IK1400005 - Driveline Information Center and Troubleshooting Procedures](#)

### Troubleshooting Flowchart





### Engine Vibration Information

**Table 1 - Engine Mount Troubleshooting and Repair**

#### Description

Engine Vibration on all Engine and Chassis Types

- For MaxxForte 11/13 and N13 front engine mount information refer to Table 2 below.

#### Symptoms

- Driver may feel a vibration while steering the chassis in one direction or the other.
- Driver may feel this in the floor or steering wheel while driving in certain conditions and speed ranges.
- Driver may hear as well as feel this vibration.

#### Troubleshooting

1. Remove the lower snubber washers on the rear engine mounts and look to see if the "spool" is centered in the mount bracket.
2. Jack the rear of the engine up to remove pressure from mount to see if the "spool" or the outer portion of the rubber on the mount is torn loose or damaged.
3. Remove and inspect the front engine mounts to inspect the inner radius of the isolator for damage.

**Figure 2 - Rear Engine Mount Damage**





Isolator is damaged.

### **Resolution**

- Replace any compromised mount - there are no part number changes just get what parts catalog calls for.
- With new mounts installed, carefully let the weight of the engine down on the mounts-pay close attention to note whether the weight of the engine cocks the spool to an angle and then note whether the spool is perfectly centered.
- Loosen the bolts that assemble the rear of cab crossmember and push out the frame if it is too narrow or pull frame together if too wide to allow centering of the rear engine mount bolts and retorque the crossmember bolts.
- If the frame is still too wide at the rear engine mount area then you will need to add grade eight washers between the mount and the frame to space it inward until perfectly centered.
- If the frame is still too narrow at the rear engine mount area then you will need to measure the frame width at the front engine crossmember, again at the rear engine mount area, and lastly at the first crossmember (rear cab mount) behind the engine and document these numbers.

**Table 2 - MaxxForce 11/13 and N13 Specific Information**

### **Description**

Engine Vibration on MaxxForce® 11/13 or N13

### **Symptoms**

- Vibrations felt in the engine at idle and highway speeds.
- Driver may complain they cannot see out the side mirrors due to the vibration, particularly at idle speed in reverse.


## Resolution

- When installing a MaxxForce 11/13 or N13 engine a shoulder bolt (PN 3822703C1 or 3596321C2) must be used to align both the left and right front engine mounts.
- This will ensure correct alignment of front engine mount bushings.
- Install the shoulder bolts (as shown in Figure 5) prior to lowering the engine into the chassis.
- After the engine has been positioned and the front and rear engine mount bolts have been tightened to the appropriate torque, remove the alignment bolt from each of the front engine mounts.

**NOTE:**


If the alignment bolts are left in, it will cause an engine vibration.

Figure 4




1. Temporary Alignment Bolt
2. Engine Mount Bolts

Figure 5



- 1. Front Engine Mount Bolts (Torque: 215-237 Nm) (160-175 Lbf-ft)
- 2. Temporary Alignment Bolt

Figure 6



- 1. Front Engine Mount Bolts (Torque: 215-237 Nm) (160-175 Lbf-ft)

Cab Vibration Information

**Description**

Cab mount vibration. Applies to any vehicle model.

### **Symptoms**

- Vibrations felt in the engine or cab at idle and/or highway speeds.
- Driver may complain they cannot see out the side mirrors due to the vibration.

### **Resolution**

- Check the air bag height on the rear cab mounts.
- Check the torque and condition of the front cab mounts.

---

---

## Mirror Shake - Engine and Cab Vibration Diagnostics Complete

### **Description**

Mirror shakes and vibrates at any engine speed. Applies to any vehicle model.

### **Symptoms**

- Mirror shake at any engine speed.
- Shake may be worse while in reverse.

### **Service Parts Information**

Self-adhering weights

### **Supplier Service Information**

Lang Mekra Mirror Service Information

- <http://www.lang-mekra.com/servicemanuals.html>

### **Resolution**

- Inspect to make sure upper flip out arm has good rubber grommet.
  - These have been known to wear out.
- Remove the mirrors and add weight using self-adhering weights to the back side of the mirror.
  - It may take up to 16oz of weight on each mirror.

Hide Details	Feedback Information
	Viewed: 6008 Helpful: 733 Not Helpful: 1569
No Feedback Found	

Copyright © 2015 Navistar, Inc.