

BAHAMAS, BOLIVIA, BELIZE, CANADA, CHILE, TAIWAN, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR, EL SALVADOR, TRINIDAD AND TOBAGO, UNITED STATES, URUGUAY, VENEZUELA, MEXICO, ARUBA, NICARAGUA, PERU, CUTAGAO, GUAM, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, Document IK1201159 Countries: ID: KOREA, SOUTH KOREA, PANAMA Availability: ISIS, Bus ISIS, FleetISIS, Body Builder Revision: 5 Maior **ENGINES** Created: 7/22/2014 System: Current Last English 10/23/2015 Language: Modified:

Less Info

Alex

Buzgau

Author:

Hide Details			C	oding Information			
Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
GÐ		View My Bookmarks	<b>*</b>		<b>P</b>	24	5

Other

Languages:

Viewed:

NONE

7598

Title: SPN 3251 FMI 2 & 21 DPFDP above or below desired level diagnostics

Applies To: 2010 + MaxxForce DT, 9, 10, N9 & N10 (ESN 3,300,000 and later)

### **CHANGE LOG**

NOTE: DO NOT delete this Change Log. If this iKNow Article is being revised, please type in the text box below what has changed in the article. The change log is meant for Dealers to be able to see what has updated/changed in the article.

Dealers: Please refer to the change log text box below for recent changes to this article:

10/23/2015 - Updated warranty information section.
6/1/2015 Author updated for feedback purposes.
12/22/2014 - Steps updated for clarification.
10/21/2014 - Snap Throttle note added.

## **DESCRIPTION**

Supplemental diagnostics for fault code SPN 3251 FMI 2 & 21 DPFDP above or below desired level

#### SYMPTOM(s)

### Diagnostic Trouble Code(s) & Dashboard Indicator Light(s):

- SPN 3251 FMI 2 & 21 DPFDP above or below desired level (active, inactive or pending)

# Customer Complaint(s):

- Frequent regens
- Engine warning light
- Unable to regen
- Black smoke

#### **DIAGNOSTIC STEP(s)**

Step	Action	Decision		
		A: Yes repair and retest for the fault.		
		B: No and high DPFDP is suspected due to differential pressure spikes proceed to step 2.		
	·	C: No and low DPFDP is suspected due to rapid drops in differential pressure proceed to step 3.		

Step	Action	Decision		
2	Do a DPF reset in Service Maxx (See figure 1) > parameters> CDPF reset> yes> program	Yes: Perform symptom 3 (MEDIUM DUTY): SPN 3719 OR SPN 3936 ACTIVE ONLY OR FREQUENT REGENS (MORE THAN ONE PARKED REGEN PER DAY) in the Aftertreatment Diagnostic Manual 0000003081.  No: Repair completed.		

Step	Action	Decision
3		

Yes: Continue symptom 5 (MEDIUM DUTY) : BLACK SMOKE in the Aftertreatment Diagnostic Manual 0000003081 Test with snap accel test to check for black smoke, is black smoke present? No: Remove DPF and inspect for defect and compare to reuse guidelines in Aftertreatment Diagnostic Manual 0000003081 if no defects found then go to step 4.

Step	Action	Decision
4	FMI 2 DPFDP above or below desired level is	Perform the pin drop test using <b>ONLY</b> an FSX approved testing rod to determine if there is internal DPF melting or defect. If no defects found then go to step 5.

Step	Action	Decision		
5	Reinstall the LIPE and refest for the issue	If the issue has been resolved it was most likely a mounting or gasket issue.		




Figure 1:

#### **REMOVAL & INSTALLATION PROCEDURE**

Follow Exhaust aftertreatment and diesel particulate filter (DPF) service manual for your vehicle (S07003 - S07006)

## WARRANTY INFORMATION

#### Warranty Claim Coding:

Group:	12000 - ENGINES		
235 - Diesel Particulate Filter			
Noun:	575 - Sensor, DPF differential pressure		
	577 - Tube, DPF differential pressure sensor		

## Standard Repair Times:

Description	Chassis	Engine	Qualifier 1	Qualifier 2	SRT	Hours
DIESEL PARTICULATE	7000	All Engines	Horizontal Mount Under Cab		A12-4930	<u>Click</u>
FILTER (DPF), R & R	Models, ALL	All Engines	Horizontal Mount Under Frame		A12-4932	Here for Hours
	Models, ALL	All Engines	Vertical Mount		A12-4934	
ELECTRONIC ENGINE	HC Bus	MAXXFORCE DT/9/10 2010 Emissions			E12-2953T	Click Here
CONTROL SYSTEM OR SCR SYSTEM (FAULT	CE / BE	MAXXFORCE DT/9/10 2010 Emissions			GY12-2953T	for Hours
000000000000000000000000000000000000000	CE / BE	N 9/10			GY12-2953TS	riouro
Sensor/Tubes Diagnostics)	RE	MAXXFORCE DT/9/10 2010 Emissions			I12-2953T	
	4300,4400	MAXXFORCE DT/9/10 2010 Emissions			KL12-2953T	
	4300,4400	N 9/10			KL12-2953TS	
		II		II .	ll .	ll l

	7300, 7400, 7500	MAXXFORCE DT/9/10 2010 Emissions			M12-2953T	
	7300, 7400, 7500	N 9/10			M12-2953TS	
DPF DIFFERENTIAL PRESSURE SENSOR, REPLACE	Models, ALL	All Engines			A12-8575A	Click Here for Hours
EXHAUST PRESSURE	Models, ALL	MAXXFORCE DT/9/10	2010 Emissions	ONE		Click
DIFFERENTIAL SENSOR	Models, ALL	MAXXFORCE DT/9/10	2010 Emissions	вотн	A12-6577T-20	Here for Hours

# OTHER RESOURCES

# Aftertreatment Resource Center

Alide Details	Feedback Information
	Viewed: 7597
	Helpful: 24
	Not Helpful: 5
No Feedback Found	

Copyright © 2015 Navistar, Inc.