

Technical Service Bulletin

15 Engine rattling noises at cold start - V6 3.0 TFSI

15 15 26 2039995/1 March 3, 2015.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2011 - 2014	All	V6 3.0 TFSI

Condition

Rattling noises are heard from the timing chain drive for about 1-3 seconds after the first engine start of the day.

Technical Background

The noises are caused by one of the upper chain tensioners. The noises do not lead to damage.

Production Solution

Improved chain tensioner.

Service

- 1. Verify condition by observing engine sound during cold start.
- 2. If the rattling noise comes from the area of the timing chains (back of the engine) for 1-3 seconds after the first start of the day, replace both upper chain tensioners of bank 1 and bank 2 with the optimized chain tensioners.



Technical Service Bulletin

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	1536				
Damage Code:	0010				
Labor Operations:	Chain tensioner remove+reinstall (See Elsa for SRT specific to model)	1536 20XX	XX TU		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	0121 0002	10 TU		
	Road test after service procedure	0121 0004	10 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty C	Online for DADP allowar	nce details)		
Claim Comment:	As per TSB #2039995/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
06E109217AH	Chain tensioner bank 2	1
06E109218AJ	Chain tensioner bank 1	1

Additional Information

All parts and service references provided in this TSB (2039995) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.