



# Technical Bulletin

---

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All except Routan	2011-2015	All	All	All	All

## Condition

92 15 01 February 23, 2015 2037322 Supersedes Technical Bulletin V921402 dated May 30, 2014 to include model year 2015 applicability.

Washer Level Sensor

## Technical Background

The sensitivity of the washer solvent level sensor (G33) can be affected by the type, concentration, and the presence of additives in the washer solvent currently in the tank. The operation of the level sensor relies on the composition of the solvent to provide an accurate message on the solvent level. Incorrect concentration and the presence of additives can contaminate the sensor and reduce its sensitivity.

## Production Solution

N/A.

# Technical Bulletin

---

## Service

The indicator lamp in the instrument panel for washer fluid remains illuminated and the washer reservoir is full. Validate the washer reservoir is full with the proper washer solvent. Refer to Elsa for proper fluid type and fluid quantities under repair manual, maintenance, fluid capacity table. If the fluid is found to be incorrect, drain the fluid, remove the sensor, and clean with cleaner (D-009-401-04) or equivalent. Reinstall the sensor, top off washer reservoir with proper fluid and validate that the indicator lamp in the instrument panel is no longer illuminated.

Non-approved fluids can cause residues to form on the sensor which causes the washer fluid lamp to remain on when reservoir is full. A picture of the sensor in question (G33) and a picture of the approved cleaner (D-009-401-04) are provided below.





# Technical Bulletin

---

## Warranty

Information Only.

## Required Parts and Tools Additional Information

**All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.**