



Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Passat	2015	2.0L TDI (CVCA)	All	All	All
Golf	2015	2.0L TDI (CRUA)	All	All	All

Condition

26 15 01 January 21, 2015 2039436

Ad Blue Warning and or MIL ON - Ad Blue Leakage at Reductant Injector

The following fault code may also be stored in the ECM Fault Memory:

DTC	Description
P20E8	Reductant Pressure Too Low

Technical Background

Welding process issues of the reductant line connector to the supply line may cause Ad Blue leakage at the reductant injector.

Production Solution

Improved parts implemented into production.

Technical Bulletin

Service

Inspect the connection of the reductant supply line connector at the reductant injector in the engine compartment. If white crystalized (dried) Ad Blue is found at the reductant injector (see Figure 1 & 2), it will be necessary to replace the reductant supply line.



Figure 1



Figure 2

Thoroughly clean the area of the reductant supply line connection with water to remove the crystalized Ad Blue. Replace the reductant supply line.



Note:

It is not necessary to replace the reductant injector.



Technical Bulletin

Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Jetta, Passat	2015	2.0L TDI (CVCA)	All	All	All
Golf	2015	2.0L TDI (CRUA)	All	All	All
SAGA Coding					
Claim Type:	Use applicable Claim Type ¹⁾				
Service Number:	Damage Code	HST		Damage Location (Depends on Service No.)	
2684	0050	--		Use applicable when indicated in Elsa (L/R)	
Parts Manufacturer	Golf, Passat		WVO ²⁾		
	Jetta		3ME ²⁾		
Passat					
Labor Operation ³⁾ : Reductant Agent Supply Line Remove + Install			26841905 = 50 TU		
Labor Operation ³⁾ : Clean Up of crystallized Ad Blue			26842999 = 20 TU		
Labor Operation ³⁾ : Reductant Agent Inspect + Add			26883500 = 30 TU		
Jetta, Golf					
Labor Operation ³⁾ : Reductant Agent Inspect + Add			26883500 = 30 TU		
Labor Operation ³⁾ : Clean Up of crystallized Ad Blue			26842999 = 20 TU		
Labor Operation ³⁾ : Reductant Agent Supply Line Remove + Install			26841999 = 80 TU		



Technical Bulletin

Causal Part: Supply Line for Reduction Agent		See Parts Table Below
Diagnostic Time ⁴⁾		
GFF Time expenditure	01500000 = 20 TU max.	YES
Road Test	01210002 = 00 TU 01210004 = 00 TU	NO
Technical Diagnosis:	01320000 = 00 TU max.	NO
Claim Comment: Input "As per Technical Bulletin 2039436" in comment section of Warranty Claim.		
<p>¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only</p> <p>²⁾ Code per warranty vendor code policy.</p> <p>³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.</p> <p>⁴⁾ Documentation required per Warranty Policies and Procedures Manual.</p>		



Technical Bulletin

Required Parts and Tools

Model	Part Number	Description
Passat	561 131 984 D	Supply Line for Reduction Agent
Golf	5Q0 131 984 E	Supply Line for Reduction Agent
Jetta	5C0 131 984 B	Supply Line for Reduction Agent

Tool Description	Tool No:
Midtronics Battery Tester/Charger	InCharge 940 (INC-940) or GRX3000VAS
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X with ODIS Service with: current online updates

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.