

Tech Tips

TT 21-10-02

Date: July 1, 2010

All 2008-2015 Vehicles with 2.0 TSI Engine (CCTA, CBFA) –
Fault Codes P0299, P0234, or P0236

June 19, 2015: Update to Model Year/Application.

Check that the roll pin located in the turbocharger exhaust housing hasn't backed out, allowing the wastegate valve and lever to drop into the housing (see attached pictures). The wastegate lever can become seized in the open or closed position, causing either an underboost or overboost condition. This condition can be intermittent as well making it hard to duplicate the fault. Inspect the wastegate lever for approx. 3mm of clearance between the bottom of the lever and the turbocharger housing. If there is no gap then the turbo must be replaced.

