

#### 20 MIL on (DTC P045600 - EVAP system leak detected NVLD (very small leak))

20 15 48 2035073/10 October 15, 2015. Supersedes Technical Service Bulletin Group 20 number 15-46 dated May 15, 2015 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A3 Sedan	2015	000001 - 122823	With NVLD	
A3 Cabriolet	2015	000001 - 122834	With NVLD	
A4	2013 - 2014	All	With NVLD	
A4	2015	A000001 - A106622 N000001 - N033839	With NVLD	
allroad	2013 - 2014	All	With NVLD	
allroad	2015	000001 - 110433	With NVLD	
A5	2013 - 2014	All	With NVLD	
A5	2015	000001 - 048917	With NVLD	
RS 5	2013 - 2014	All	With NVLD	
RS 5	2015	900001 - 901489	With NVLD	
A5 Cabriolet	2013 - 2014	All	With NVLD	
A5 Cabriolet	2015	000001 - 008878	With NVLD	
Q5	2013 - 2014	All	With NVLD	
Q5	2015	000001 - 111804	With NVLD	
A6, A7	2012 - 2015	All	With NVLD	
A6, A7	2016	000001 - 009518	With NVLD	
RS 7	2012 - 2015	All	With NVLD	
RS 7	2016	900001 - 900125	With NVLD	
A8	2011 - 2014	All	With NVLD	
A8	2015	000001 - 033269	With NVLD	

© 2015 Audi of America, Inc.

all rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



#### Condition

REVISION HISTORY				
Revision	Date	Purpose		
10	-	Revised header data (Added VIN breaks)		
		Revised <i>Required Parts and Tools</i> (Updated pressure switch part numbers)		
9	5/15/2015	Revised Warranty (Added labor operations)		
		Revised <i>Required Parts and Tools</i> (Updated filter part number for Q5 hybrid)		
8	4/29/2015	Revised Production Solution (Added filter information)		
		Revised Service (Added instructions)		
		Revised Warranty (Updated labor operations)		
		Revised Required Parts and Tools (Added filter part numbers)		

- MIL on.
- DTC P045600 (EVAP System Leak Detected NVLD (very small leak)) is stored in the engine control module (ECM), J623 (address word 01).
- Drivability is not affected.

#### **Technical Background**

The NVLD pressure switch may erroneously detect a very small leak.

#### **Production Solution**

New NVLD pressure switches and NVLD filters in production.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



#### Service

- 1. Ensure that **DTC P045600** (EVAP System Leak Detected NVLD (very small leak)) is stored in the engine control module (ECM), J623 (address word 01). If DTC P045600 is not present, this bulletin does not apply.
- 2. Replace the NVLD pressure sensor G400 and the NVLD filter with the latest part number available (Figure 1).



Figure 1. NVLD pressure sensor (left) and NVLD filter (right).



Read the following information for correct installation of the NVLD switch grommet. The following information applies only if the sensor is directly installed into the charcoal canister.

• Align grommet and sensor outer edges (Figure 2).



Figure 2. Align grommet and sensor outer edges.

© 2015 Audi of America, Inc.

Page 3 of 8

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



• To aid installation, wrap several (~10) layers of vinyl tape behind the grommet to ensure that it does not slip during installation (Figure 3 and Figure 4).



Figure 3. Wrapping vinyl tape behind the grommet.



Figure 4. Vinyl layer supporting grommet.

© 2015 Audi of America, Inc.

Page 4 of 8

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



• Apply a small amount of grease to create a film on the outer surface of the grommet before installing the sensor (Figure 5).



Figure 5. Grease film on outer surface of grommet.

• When the sensor and grommet have been correctly installed, the grommet and canister will be flush (Figure 6). At this point, the vinyl tape can be removed (or it can be left in place).



Figure 6. Correctly-installed sensor and grommet.

© 2015 Audi of America, Inc.

Page 5 of 8

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



 An incorrectly-installed sensor and grommet (Figure 7) can cause an EVAP leak and repeat failures. Issues can occur when the NVLD switch is pressed too far into the canister, then pulled back out in an attempt to align the NVLD switch with the mounting holes.

Do not apply any lubricant between the sensor and the grommet.



*Figure 7. Plastic port extending past the grommet (A) causing installation issues (B).* 

U Note:

Due to the functionality of the new tank leak diagnostic system (NVLD), it is not possible to check the system using a basic setting or an output diagnostic test mode like the previously-used LDP system.

Note: Always use a VIN to search parts in ETKA.

#### Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2041		
Damage Code:	0040		
Labor Operations:	For A3 and A3 cabriolet:		
	NVLD pressure switch remove + reinstall	2041 1950	20 TU
	Rear wheel housing liner remove + reinstall	6676 1900	40 TU
	For A4, A5, A5 cabriolet:		
	NVLD pressure switch remove + reinstall	2041 1950	10 TU
	Activated charcoal filter remove + reinstall	2025 1910	50 TU
	Rear wheel housing liner remove + reinstall (includes time for filter replacement)	6676 1999	40 TU

© 2015 Audi of America, Inc.

#### Page 6 of 8

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



	For A6 and A7:			
	NVLD pressure switch remove + reinstall	2041 1950	10 TU	
	Activated charcoal filter remove + reinstall	2025 1900	40 TU	
	Rear wheel housing liner remove + reinstall (includes time for filter replacement)	6676 1999	40 TU	
	r Q5 and Q5 hybrid:			
	NVLD pressure switch remove + reinstall	2041 1950	10 TU	
	Activated charcoal filter remove + reinstall	2025 1910	50 TU	
	Rear wheel housing liner remove + reinstall (includes time for filter replacement)	6676 1999	40 TU	
	For A8:			
	NVLD pressure switch remove + reinstall	2041 1950	30 TU	
	Wheel remove + reinstall	4405 1900	20 TU	
Diagnostic Time:	GFF – Checking and clearing fault codes included in existing labor operations	0150 0000	Time stated on diagnostic protocol	
			(Max 20 TU)	
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)			
Claim Comment:	As per TSB #2035073/10			

All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

© 2015 Audi of America, Inc.

Page 7 of 8

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



### **Required Parts and Tools**

Part Number	Part Description	Quantity
5Q0906253B or 5Q0906253C(For A3 sedan)	Pressure switch	1
(Backwards-compatible for all A3 sedans)		
8K0906253K (For A8, Q5 hybrid, and	Pressure switch	1
A3 cabriolet)		
8K0906253L (For A4, A5, A5 cabriolet, Q5, A6, and A7)	Pressure switch	1
1C0906621A (For A3 sedan and A3 cabriolet)	Filter	1
8R0906621E (For A8)	Filter	1
8F0201997D (For A5 cab)	Filter	1
8R0201997T (For Q5)	Filter	1
8R0906621F (For Q5 hybrid)	Filter	1
4G0201997BA (For A6,A7)	Filter	1
8K0201997AL (For A4,A5)	Filter	1

#### **Additional Information**

All parts and service references provided in this TSB (2035073) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2015 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.