

## Technical Service Bulletin

#### 91 Antenna technical problem message (DTC 02617)

91 15 13 2041940/1 September 23, 2015.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5	2016	All	Not Applicable

#### Condition

- The following message is displayed in the driver information panel when in the SiriusXM band:
  - "ANTENNA A technical problem has occurred. Please contact your Audi dealer." (Figure 1).
- · Audio from the satellite radio is present.
- DTC 02617 (Satellite antenna) is stored in the radio (address word 56) with fault code 11 (Open circuit).



Figure 1. ANTENNA message.

### **Technical Background**

Visually, the MMI and MIB antennas are the same, but each antenna draws a different amount of current. For this reason, if an MIB antenna has been installed on a vehicle with an MMI radio, it causes an open circuit DTC. The open circuit DTC will be set on an MMI radio if the current draw from the antenna falls below 60mA.

- A MIB antenna draws 55mA (+/- 10mA) 4G0-035-503-K
- A MMI antenna draws 110mA (+/- 10mA) 4G0-035-503-J

#### **Production Solution**


Not applicable.

# Audi

## Technical Service Bulletin

#### **Service**

- 1. Check the current consumption of the shark fin antenna through ODIS GFF.
- 2. In ODIS GFF, access the measured value blocks of the radio (address word 56) (Figure 2).



**Figure 2.** Access radio measured value blocks by right-clicking the radio module (1), then selecting Guided Functions (2), then selecting Checking MVB (RG.91) and clicking Perform. (Shown for MMI 3G+.)

3. Select measuring value -3- Integrated digital tuner (if available) (Figure 3).

#### Which measuring value should be displayed?

- 1 Radio general
- 2 Antennas
- 3 Integrated digital tuner (if available)
- 4 Inputs
- 5 Cancel

Figure 3. Select measuring value -3- Integrated digital tuner (if available)

- 4. Check the current consumption of the satellite radio antenna (MVB 20.3 for MMI 3G+; MVB 9.3 for CAN radio) (Figure 4):
  - If the current consumption shown on an MMI system is between 40mA 100mA, proceed to step 5.
  - If the current consumption of the antenna is above 100mA, this TSB does not apply. Continue to diagnose
    the concern outside of this TSB.



# Technical Service Bulletin




Figure 4. Check the current consumption of the satellite radio antenna. (Shown for MMI 3G+.)

5. Remove the satellite radio antenna and inspect the part number. If an MIB antenna (with a K suffix part number) is installed on an MMI system, replace the antenna with an MMI antenna (with a J suffix part number) (Figure 5).



**Figure 5.** MIB antenna with K suffix part number 4G0-035-503-K (A), and MMI antenna with J suffix part number 4G0-035-503-J (B).

# Audi

# Technical Service Bulletin

#### **Warranty**

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	9138				
Damage Code:	0012				
Labor Operations:	For A4: GPS antenna remove+reinstall	9113 1900	160 TU		
	For allroad: GPS antenna remove+reinstall	9113 1910	190 TU		
	For A5: GPS antenna remove+reinstall	9113 1900	440 TU		
	For all: GPS antenna paint new part	9113 6100	50 TU		
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 100 TU)		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	0121 0004	10 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online fo				
Claim Comment:	As per TSB #2041940/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## **Required Parts and Tools**

Part Number	Part Description	Quantity
4G0035503J	MMI antenna	1

### **Additional Information**

All parts and service references provided in this TSB (2041940) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.