A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the <u>Elsa Newsletter</u> section in the Technician References menu.

VW Elsa Newsletter



Das Auto.

Edition 144: July 13, 2015



Wiring Diagrams Updates

i-Wire has a faster search engine.



To access i-Wire, login to ServiceNet.

Workshop Equipment Tool Storage Application Launch

VWGoA is proud to inform you of the launch of the recently announced Workshop Equipment Tool Storage Application (TSA), reference VSE-15-10 – Workshop Equipment Tool Storage Application Rollout. This application was developed through feedback provided by dealerships during National Dealer Meetings & in dealership demonstrations, dealership pilots, industry best practice studies, and in collaboration with the Technician Advisory Board (TAB).

The TSA is a highly intuitive, customizable tool storage management system that provides functionality necessary to better manage your Service Tools & Equipment inventory through the use of many customizable features.

Some of these features include:

- Enhanced accountability through tool check out / in.
- Customizable Minimum Required Tool (MRT) placement provides dealerships with the ability to custom place tools to best suit their individual needs.
- Ability to upload optional and locally procured tool inventory.
 - Multiple tools can be uploaded through excel.
 - o Individual tools can be uploaded as needed or at time of purchase.
- Individual dealership administrative rights.
 - The dealership administrator assigns and manages users.
- Ability to report missing or unserviceable tools.
- Downloadable Excel tool storage indexes.
- Ability to add comments for each tool in the inventory.
- Downloadable usage report.
- Downloadable Minimum Required Tool list and tool storage indexes.
- Available through the Service Tools & Equipment website.

To begin using the Workshop Equipment Tool storage Application, please refer to the User Quick Start Guide, VSE-15-12 – Tool Storage Application (TSA) – Startup Guide, located in Service Net under the Workshop Equipment tab in Communications. Back to top

Technical Bulletins

01 15 15 · 2040171 Supersedes Technical Bulletin V011512 dated May 19, 2015 to update the technical diagnosis answer to yes on the 4th warranty table.

MIL ON Camshaft Position Faults P0011 and or P0016 Stored in Fault Memory

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat, Jetta, Beetle, Beetle Convertible	2015	2.0L TDI (CVCA)	All	All	All
Golf, Golf SportWagen	2015	2.0L TDI (CRUA)	All	All	All

DTC	Description
P0011	"A" Camshaft Position - Timing Over-Advanced or System Performance Bank 1
P0016	Crankshaft Position - Camshaft Position Correlation Bank 1 Sensor A

The camshaft adjuster control valve may stick causing camshaft position faults. **Production Solution:** Measures implemented into production.

01 15 16 · 2041112 Update Programming, MIL ON, DTC P0138 Stored in the ECM Fault Memory						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	
Beetle, Beetle Convertible	2013– 2014	2.0T (CPPA,CPLA)	All	All	All	
Jetta	2013– 2014	2.0T (CPPA,CPLA) 1.8T (CPKA,CPRA	All	All	All	
Passat 2014		1.8T (CPKA,CPRA)	All	All	All	
The following fault code will be stored in the ECM Fault Memory:						
DTC Description						



Back to top

87 15 08 - 200 2014	05566 Super 4. Updated to H	sedes Techr o add new n IVAC, Unple	nical Bulletir nodels and easant Odo	n V871402 date new model yee or	ed April 18, ar.
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All (except Routan)	ll Routan) 2000–2016 All		All	All	All
Unpleasant odor is coming from Heating and Ventilation system. Odor mainly occurs after vehicle has been sitting (unused) at least 5 hours and within 20 to 60 seconds after vehicle is first started. Note:					
This Bulletin complaint a stated in the	may only be nd within 12 Warranty Po	applied as months of t licy. (See see	"one time o he original ction 1.3 Ge	only" for vehicle vehicle in-servi eneral Guidelin	es with the ce date as es/ Start of
Any fu	iture complai	warranty ints will be c	y period) 1t the expen	se of the custor	ner.
	Produ	ction Solutio	n: Not appl	icable	

87 15 09 - 2038368 Supersedes Technical Bulletin V871412 dated December 8, 2014 to include Golf SportWagen applicability.

Air Conditioning Does Not Cool and or Compressor is Noisy

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf, GTI, Golf SportWagen	2015	All	All	All	All

One or more of the following conditions are exhibited:

• The air conditioning does not cool, or the cooling performance is very weak.

• The air conditioning system cools, but the compressor is noisy. The noise is characterized as a grinding or groaning noise.

- Either symptom may be intermittent.
 - No DTCs are stored.

Production Solution: Final production countermeasures pending.

Pending Service Solutions

No new Pending Service Solutions this week.

Back to top

Tech Tips

90·11·10 Vehicles – Instrument Cluster Production Mode July 10, 2015: Update to Model Year Applicability.						
Model(s)	Year	Eng.Code	Trans.Code			
All	2006–2015	All	All			

During PDI, or after installation of a replacement cluster, "Pro" may be displayed in place of the odometer. The high beam indicator may be flashing in the instrument cluster as well. This indicates the cluster is in Production mode. Production mode is not the same as "Transport" mode.

To remove Production mode go into VSD>Address 17 – Instrument Cluster>Adaptation>Select either channel 22 if available, or the listing for Production Mode. Toggle Production mode 'OFF">save and accept>back out of address 17. Cycle the key and check the cluster display.



Campaigns

Campaign Tip - Safety Recall 28H1 28H1 - Ignition Switch (WIN Module)

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Routan	2009–2010	All	All	All	All

Scan tool software must be at v13.04.15 or higher or programming the new WIN/ignition switch will not be possible. A reminder about this is found in the recall work procedure:

NOTE:

The following requirements MUST be followed during the adaptation of the new WIN and keys:

- This procedure requires the WiTECH Desktop Client. DO NOT attempt to perform WIN and/or key adaptation using the StarMOBILE Desktop Client.
 - The WiTECH Desktop Client software <u>must be v13.04.15 or higher</u> to program the WIN and keys (FOBIKs) successfully.
- Battery voltage must consistently remain between 13.2V and 13.5V during the programming process. Use the InCharge 940 (or equivalent) to maintain proper system voltage.
 - For this procedure, the WIN and FOBIKs are pre-programmed together. Follow the instructions below to avoid damaging the new WIN and/or FOBIKs.

Updates

No new updates this week.

Suggestions

Please send comments or suggestions to: www.workshopinformation@vw.com

Back to top

© 2015 Volkswagen of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by

any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.