

A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the [Elsa Newsletter](#) section in the Technician References menu.

# VW Elsa Newsletter



Edition 134: May 5, 2015

## Content

- [Reminder Tips - Searching for TB's in VW Google](#)
- [Technical Bulletins](#)
- [Pending Service Solutions](#)
- [Tech Tips](#)
- [Campaigns](#)
- [Updates](#)
- [Suggestions](#)



## Reminder Tips - Searching for TB's in VW Google

**Note:** A quick video on finding Technical Bulletins on Elsa and VW Google can also be found in the ElsaPro section of the **VW IQ website**.  
Click to view: [Accessing Technical Bulletins from Elsa Pro](#).

**Video update:** TB's can be accessed on Elsa using either a VIN or building a vehicle with a 6 digit model code.

Users can find all Technical Bulletins (TB) on VW Google using the following search methods  
(The example TB used is **"26-12-07 - Ad Blue Filling at Delivery (2031040/1)"**):

1. Using the TB group number **(26-12-07)**:

Searching by group number allows the user to browse all the TB's available for that specific group. There are three ways to use the group search:

- A. By repair group # (26)
- B. By Repair Group # + Publishing Year (26-12)
- C. By Repair Group # + Year + Publishing # (26-12-07)

Example (Repair Group # + Publishing Year):

**Search Results** powered by Google

Warning: The VW Google search tool does not search information clearly to ensure it applies to the vehicle you are working on. No void your warranty claim.

Search: **26-12** [Search]

Results for "26-12"

**Tech Bulletins, RVUs** 3 of 11 results | ➡

- 26-12-02TT - AdBlue Level Reset Procedure**  
... TT 26-12-02 Date: November 9, 2012 2012-2013 Passat TDI AdBlue Level Reset Procedure February 14, 2014: Upd
- 26-12-01TT - Secondary Air Injection Sys**  
... TT 26-12-01 Date: May 11, 2012 2005 Sportwagen with 2.5L Engine Secondary Air Injection System ...
- 26-12-05 - Catalytic Converter Replacement Guidelines**  
26 12 05 July 18, 2012 2010271 Supersedes TB 260701 dated September 13, 2007 to update warranty table claiming information. ...

**All Documents From RG 26 published in 2012**

**On-car analysis list fr please contact VW H**

Models	MY	Engine	Tr
Jetta, Jetta SW, Golf, Beetle, Beetle Conv, Passat	14	2.0TDI CJAA / CKRA	A
Jetta, Passat	14 - 15	All	A
Passat	12 - 15	All	A

2. Or the TB title:

**Search Results** POWERED BY Google

**Warning:** The VW Google search tool does not search clearly to ensure it applies to the vehicle you are working on. Please use the tool to void your warranty claim.

Search

Results for "Ad Blue Filling at Delivery"

You could try:

[Add Blue Filling at Delivery](#)

**Tech Bulletins, RVUs** 1 of 1 results | ➡

[26-12-07 - Ad Blue Filling at Delivery](#)

... Blue Filling at Delivery The checking and filling of Ad ... The Ad Blue tank capacity in the Passat is 19.5L. During assembly the tank is filled with 18.5 ...

**On-car analysis please contact**

Models	MY	Eng
Jetta, Jetta SW, Golf, Beetle,		2.0

3. Or the TB instance:

**Search Results** POWERED BY Google

**Warning:** The VW Google search tool does not search clearly to ensure it applies to the vehicle you are working on. Please use the tool to void your warranty claim.

Search

Results for "2031040/1"

**Tech Bulletins, RVUs** 1 of 1 results | ➡

[26-12-07 - Ad Blue Filling at Delivery](#)

Model(s), Year, Eng. Code, Trans. Code, VIN Range From, VIN Range To.  
Passat, 2.0L TDI (CKRA), All, All, All, All. 26 12 07 September ...

**On-car analysis please contact**

Models	MY	Eng
Jetta, Jetta SW, Golf, Beetle,		2.0

4. Or by Key word search:

# Search Results

powered by Google

**Warning:** The VW Google search tool does not search information based on VIN clearly to ensure it applies to the vehicle you are working on. Not doing so could void your warranty claim.

Search

Results for "ad blue"

You could try:

[add blue](#)

## Tech Bulletins, RVUs

3 of 5 results |

[26-14-01TT - Ad Blue® Reset Procedure](#)

... Date: April 18, 2014 2011-2014 Touareg - 3.0L TDI Ad Blue® Reset Procedure ...

To reset the Ad Blue level light after the tank has been filled: ...

[26-12-02TT - AdBlue Level Reset Procedure](#)

... 3) Go to Control Module OBD, Basic Settings select Check of SCR efficiency, press blue forward arrow on the bottom right. ...

[26-11-03TT - AdBlue Light On with Tank Full](#)

Page 1: Tech Tips Page 1 of 1 ver1.2 © 2014 Volkswagen Group of America, Inc. All rights reserved. Information contained ...

## On-car analysis list from September 2014 please contact VW Helpline before

Models	MY	Engine	Trans	T
Jetta, Jetta SW, Golf, Beetle, Beetle Conv, Passat	14	2.0TDI CJAA/CKRA	All	EGS
Jetta, Passat	14-15	All	All	Car-N
Passat	12-15	All	All	B-Pit
				Front win during causing

[Back to top](#)

## Technical Bulletins

**26 15 03 - 2038752 Supersedes Technical Bulletin V261502 dated April 13, 2015 to correct Golf vendor code.**

**MIL ON, Exhaust Flap Faults P048B, P048E, P0475, P0478, P0477 stored in ECM Fault Memory**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf	2015	2.0L TDI (CRUA)	All	All	All
Passat, Beetle, Beetle Convertible, Jetta	2015	2.0L TDI (CVCA)	All	All	All

The new Generation III TDI engines have an exhaust flap that is welded into the exhaust pipe assembly. If faults for the flap electronics are stored, it is not necessary to replace the complete pipe. Replacement electronics components are available.  
(See Technical Bulletin for DTC Codes and images)

**Note:**

As an Electrostatic Discharge (ESD) sensitive part, the actuator must be removed from the ESD bag and handled in an ESD safe area.

If the actuator has been dropped on the floor, it must be scrapped.

**Production Solution:** Not Applicable.

**01 15 09 - 2040057 Supersedes Technical Bulletin V011504 dated March 12, 2015 to include service regeneration time in GFF time to assist SAGA claiming.**

**Update Programing, MIL ON, Diesel Particulate Filter (DPF) Faults P2458, P2463 Stored in ECM Fault Memory**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat, Jetta, Beetle, Beetle Convertible	2015	2.0L TDI (CVCA)	DSG (02E)	All	All
Passat, Jetta, Beetle, Beetle Convertible	2015	2.0L TDI (CVCA)	Manual (02Q)	All	All
Golf	2015	2.0L TDI (CRUA)	DSG (02E)	All	All

Golf	2015	2.0L TDI (CRUA)	Manual (02Q)	All	All
<p>Deviation between the calculated and the actual soot mass of the particulate matter trap causing P2463.</p> <p>Incorrect data for the particulate matter trap regeneration time causing P2458. (See Technical Bulletin for Fault Codes)</p> <p><b>DO NOT</b> diagnose or replace components due to DPF faults <b>before</b> performing the update function as explained in this bulletin.</p> <p><b>Production Solution:</b> Improved software implemented into production.</p>					

<p><b>21 15 04 - 2026771 Supersedes T. B. V211501 dated January 15, 2015 to remove engine cover labor operation contained in diesel particulate filter labor operation.</b></p> <p><b>Engine Lacks Performance, Engine Warning Light ON, DTCs P2563, P2564, P0299 or P20D8 Stored in ECM Fault Memory</b></p>					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Jetta Wagon	2009	2.0L TDI (CBEA)	All	All	All
Jetta Sedan, Golf, Golf Wagon, Jetta SportWagen	2010	2.0L TDI (CJAA)	All	All	All
Jetta Sedan, Golf, Golf Wagon, Jetta SportWagen	2011– 2014	2.0L TDI (CJAA)	All	All	All
<p>Engine does not have any power and the engine warning light may be ON. One of the following DTC entries is stored in the engine control module. (See Technical Bulletin for DTC codes)</p> <p><b>Production Solution:</b></p> <p>Optimized assembly process to avoid twisted vacuum line. Increase compressor housing washer thickness. Change of material for min. flow adjustment screw. Improved vacuum diaphragm with charge pressure actuator position sensor -G581-</p>					

**53 15 01 - 2040536 Rear Quarter Panel Corrosion (U.S. Only)**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf (A5)	2006–2009	All	All	All	All
Jetta	1999–2010	All	All	All	All
Jetta Wagon	2001–2005	All	All	All	All

Corrosion is found where the rear bumper cover meets the quarter panel.

**Note:**

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual.

Documentation required per Warranty Policies and Procedures Manual.  
For vehicles outside of the Limited Warranty Against Corrosion Perforation this Technical Bulletin is for information only.



**Production Solution:** No production change required.

**93 15 01 - 2040470 High Voltage Battery Not Charging as Expected for Departure Time Set With Car-Net™ (U.S. Only)**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
e-Golf	2015	All	All	AU_FW900001	AU_FW910916

The high voltage battery may not charge as expected when a departure time has been set using the Car-Net™ app or web portal.

**Production Solution:** Improved parameters in production as of CW16/2015.

**26 15 04 - 2039436 Supersedes Technical Bulletin V261501 dated January 21, 2015 to change Golf vendor code from WWO to 3ME and update supply line front labor operation number.**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Passat, Beetle, Beetle Convertible	2015	2.0L TDI (CVCA)	All	All	All
Golf	2015	2.0L TDI (CRUA)	All	All	All

Ad Blue Warning and or MIL ON - Ad Blue Leakage at Reductant Injector  
(See Technical Bulletin for DTC Code)

**Production Solution:** Improved parts implemented into production.

## Pending Service Solutions

No new Pending Service Solutions this week.

[Back to top](#)

## Tech Tips

### **17-11-03 Oil Consumption Testing - Date: July 22, 2011 May 1, 2015: Update to Model Year Applicability.**

Model(s)	Year	Eng.Code	Trans.Code
Routan	2009-2014	All	All

#### NORMAL OIL CONSUMPTION:

- Mileage below 50,000: Normal oil consumption is one quart for each 1,000 miles driven.
- Mileage above 50,000: Normal oil consumption is one quart for each 750 miles driven.

#### TEST TO DETERMINE ENGINE OIL CONSUMPTION:

1. Operate engine to normal operating temperature.
2. Fill engine oil precisely to FULL mark on dip stick gauge.
3. Use paint pen to mark the engine oil drain plug to prevent tampering.

4. Check engine oil level after 1.000 miles driven. Refer to normal engine oil consumption listed above.

POSSIBLE CAUSES FOR EXCESSIVE ENGINE OIL CONSUMPTION:

- PCV OR CCV SYSTEM: Check the crankcase ventilation system for proper operation. Oil may accumulate in the throttle body or intake manifold. Rocker arm lubrication oil flow returns to oil pan through drain back holes in top of cylinder head. Plugged or restricted oil drain back holes may contribute to excessive oil in crankcase ventilation system.
- SPARK PLUGS: Examine all spark plugs to identify the affected cylinder(s). Spark plug on the affected cylinder(s) will usually be fouled or wet with engine oil.
- VALVE GUIDES AND VALVE STEM SEALS: Inspect valve guides on the affected cylinder(s). Replace valve stem seals on the affected cylinder(s).
- PISTON RINGS: Check piston rings on the affected cylinder(s). Piston rings may be too tight, worn, or broken or there may be carbon build up in the oil control ring.
- CYLINDER WALL: Examine the cylinder wall on the affected cylinder(s). Cylinder wall may be severely scuffed.


[Back to top](#)

**91-14-01 Car Net™ Equipped Vehicles False Outbound Calls - Date: January 17, 2014**

**May 1, 2015: Update to Model Year Applicability.**

Model(s)	Year	Eng.Code	Trans.Code
Eos, Jetta, Beetle, Passat, CC, Tiguan	2014-2015	All	All

If a 2014 Model Year vehicle equipped with the Car Net™ system experiences a customer complaint where the system is placing false outbound calls, it is possible that the cause is a loose or unplugged connector at the 3-Button Assembly in the overhead console. If this concern is verified and there is no damage to the terminal(s) or connector(s), simply secure or plug in the loose connector.



[Back to top](#)

### 93-15-01 Ensure Proper Torque Specifications when Installing High Voltage Cables on Jetta Hybrid


Model(s)	Year	Eng.Code	Trans.Code
Jetta Hybrid	All	All	All

When replacing or reinstalling High Voltage cables into the Electric Drive Power and Control Electronics JX1, insure proper torque specification of 20 Nm is used. Too much torque can cause damage to the mounting tabs within the JX1 requiring replacement of the unit.

#### Tightening Specifications, High Voltage Contacts

High voltage contacts -arrows-: 20 Nm

Threaded connection -2 and 3-: 5 Nm



## Campaigns

No new campaigns this week.

## Updates

No new updates this week.

## Suggestions

Please send comments or suggestions to: [vwg.workshopinformation@vw.com](mailto:vwg.workshopinformation@vw.com)

[Back to top](#)

© 2015 Volkswagen of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.