

Technical Service Bulletin



01 DTC P103200 (NOx sensor signal too high)

01 15 38 2041566/1 August 4, 2015.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2013 - 2015	All	V6 TDI

Condition

DTC P103200 (NOx sensor signal too high) is stored in the engine control module (ECM), J623 (address word 01).

Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the DTC codes for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition:

1. Verify the condition.
2. If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Please attach the DTC and diagnostic log to the TAC ticket.

Technical Service Bulletin



Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB (2041566) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.