

# Techstream ECU Flash Reprogramming Procedure

**Service Category** Engine/Hybrid System

**Section** Engine Control

**Market** USA

Toyota Supports  
 ASE Certification 

## Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2001 – 2016	4Runner, Avalon, Avalon HV, Camry, Camry HV, Celica, Corolla, Echo, FJ Cruiser, Highlander, Highlander HV, Land Cruiser, MR2 Spyder, Matrix, Prius, Prius C, Prius PHV, Prius V, RAV4, RAV4 EV, Sequoia, Sienna, Solara, Tacoma, Tundra, Venza, Yaris, Yaris SD MEX-Prod	
2016	Mirai	

### REVISION NOTICE

**January 15, 2016 Rev2:**

- Applicability has been updated to include 2016 model year Toyota vehicles.

**June 12, 2014 Rev1:**

- Applicability has been updated to include 2015 model year Toyota vehicles.

**Any previous printed versions of this bulletin should be discarded.**

## Techstream ECU Flash Reprogramming Procedure

### **SUPERSESION NOTICE**

The information contained in this bulletin supersedes SB No. T-SB-0064-10.

- Applicability has been updated to include 2014 model year Toyota vehicles.
- The entire bulletin has been updated to include information for Techstream 2.0.

Service Bulletin No. T-SB-0064-10 is Obsolete and any printed versions should be discarded. Be sure to review the entire content of this bulletin before proceeding.

### Introduction

Flash reprogramming allows the ECU software to be updated without replacing the ECU. Flash calibration updates for specific vehicle models/ECUs are released as field-fix procedures described in individual Service Bulletins. This bulletin details the Techstream ECU flash reprogramming process and outlines use of the Technical Information System (TIS) and the Calibration Update Wizard (CUW). Flash calibration updates can only be applied to the vehicle/ECU combination for which they are intended. ECUs have internal security that will not allow them to be programmed with another ECU's information.

### **ECU**

**Electronic Control Unit (ECU)** is a Toyota term used to describe integrated computerized devices responsible for managing the operation of a system or subsystem. For the purposes of this bulletin, the term "ECU" is used as a generic label for the following SAE J1930 standard references:

- Powertrain Control Module (PCM)
- Engine Control Module (ECM)
- Transmission Control Module (TCM)
- Or any other Toyota specific control unit

### Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–

## Techstream ECU Flash Reprogramming Procedure

### Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
00451-00001-LBL	Same	Authorized Modification Labels	1

**NOTE**

Authorized Modification Labels may be ordered in packages of 25 from the Materials Distribution Center (MDC) through Dealer Daily – Dealer Support Materials Orders.

### Required Tools & Equipment

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream 2.0*	ADE	TS2UNIT	1
Techstream Lite		TSLITEDLR01	
Techstream Lite (Green Cable)		TSLP2DLR01	

**NOTE**

- Only ONE of the Techstream units listed above is required.
- Software version 10.20.030 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.
- The Diagnostic Tester is NOT recommended for flash reprogramming. Please use Techstream or an approved J2534 interface to perform flash reprogramming updates. Visit [techinfo.toyota.com](http://techinfo.toyota.com) for more information regarding J2534 reprogramming.



SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
GR8 Battery Diagnostic Station*	<a href="#">00002-MCGR8</a>	1

**NOTE**

Additional SSTs may be ordered by calling 1-800-933-8335.

\* Essential SST.

## Techstream ECU Flash Reprogramming Procedure

---

### Techstream Preparation


#### Selecting the Correct VIM.

Techstream software requires a VIM selection before it can be used for reprogramming.

Perform the following:

1. Select *Setup* from the Techstream Main Menu screen.
2. Select *VIM Select* from the Setup drop down menu.

**Figure 1.**



## Techstream ECU Flash Reprogramming Procedure

---

### Techstream Preparation (Continued)

3. Select the correct Interface Setup from the drop down list.
  - If using Techstream 2.0, select *MongoosePro MFC*.
  - If using Techstream Lite, select Mongoose MFC, MongoosePro MFC, or MongoosePro MFC2 (green) depending on the cable being used.

**NOTE**

**Mongoose Driver MUST be installed before Mongoose selections will be available.**

**See *TIS – Diagnostics – Scantool* page for additional information.**

4. Click *OK*.

### Process Overview

Techstream ECU flash reprogramming is a 4-step process:

1. Verify the vehicle's applicability for recalibration and locate desired calibration file by performing the Techstream Health Check function.

**NOTE**

**Techstream will automatically search TIS for the appropriate Service Bulletin using the current Calibration ID from the vehicle. Calibration file links can be found embedded in the corresponding Service Bulletin.**

2. Connect the GR8 Battery Diagnostic Station using "Power Supply Mode" only.

The GR8 Battery Diagnostic Station includes a Power Supply Mode to help maintain battery voltage at 13.5 volts during ECU reprogramming.

**NOTICE**

- ECU damage may occur if the correct battery charger mode setting is NOT used.
- Refer to [Vehicle Reprogramming Tips](#) for other approved Chargers, located on TIS, *Diagnostics – Calibrations – Reference Documents*.

3. Locate appropriate calibration ID and reprogram the vehicle ECU with Techstream.

Techstream uses the Calibration Update Wizard (CUW) application to open calibration files and facilitate the ECU flash reprogramming process.

# Techstream ECU Flash Reprogramming Procedure

## Process Overview (Continued)


4. Attach the Authorized Vehicle Modification Label.

Modifications to ECU calibrations MUST be recorded and properly displayed on the vehicle using the Authorized Modification Label.

## Operation Procedure

1. Verify the vehicle's applicability for recalibration and locate desired calibration file.
  - A. Connect Techstream and establish a vehicle connection.
  - B. Click the *Health Check* button on the *System Select* tab.

Figure 2.




# Techstream ECU Flash Reprogramming Procedure

## Operation Procedure (Continued)

C. Choose desired ECU group(s) in the *Health Check* dialog box.

Figure 3.



D. Click *Next*.


## Techstream ECU Flash Reprogramming Procedure

---

### Operation Procedure (Continued)

E. Click *Continue* to view Health Check results.

Figure 4.



# Techstream ECU Flash Reprogramming Procedure

## Operation Procedure (Continued)

F. Available calibration updates are indicated by a **Yes** link in the *Cal. Update* column. Click the **Yes** link to access the appropriate Service Bulletin on TIS.

**NOTE**

- Note any DTCs stored in systems that will be flash reprogrammed.
- Clicking the **Yes** link will automatically launch TIS and perform a calibration search.

Figure 5.

The screenshot shows the Techstream software interface for a 2015 Camry. The 'Health Check Results' section is expanded to show a table of system health data. A red arrow points to the 'Update' column for the 'Main Body' system, which contains a 'Yes' link.

System	Monitor Status	DTC	Curr Conf	Pend	Hist	Test Failed	SB	Calibration	Update
Main Body	-	B1206			X		No	892210623002	Yes
		B1244			X		No		
		B2321			X		No		
Navigation System	-	B1579			X		No		
		B1570			X		No	000200290...302M A0 33	Yes
Telematics	-	B1571			X		No	59292	No
		B1572			X		No		
		B15C5			X		No		
Engine and ECT	Com						306E7000	No	
Radar Cruise	-						50625000	No	
ABS/VSC/TRAC	-						F152606100	No	
EMPS	-						8965B33271	No	
Tire Pressure Monitor	-								
Lane Departure Alert	-						8646F33020	No	
Occupant Detection	-						0E010	No	
Air Conditioner	-						886500688001	No	
Combination Meter	-						838000X82002	No	
							838000X82002	No	

G. Log in to TIS. (If already logged in, skip this step.)

# Techstream ECU Flash Reprogramming Procedure

## Operation Procedure (Continued)

- H. To review the Service Bulletin and access the calibration file, click the Service Bulletin link in the *Document Title* column of the *Calibration Search Result* portlet.

**NOTE**

Only Toyota Certified Technicians and above may access calibration files.

Figure 6.

The screenshot shows the Techstream software interface. At the top, there are navigation tabs: Library, Diagnostics, Tech Assistance, and Vehicle Inquiry. Below these are sub-tabs: ScanTool, Reprogramming, Immobilizer Reset, Key Code, Telematics, Navigation, and Tools & Equipment. The main area is divided into two sections: 'Calibrations/Configurations' and 'Reference Documents'.

The 'Calibrations/Configurations' section contains a search form with the following fields:

- Choose the criteria you would like to search by:
  - Division/Model/Year (Selected)
  - Calibration ID/Multimedia ID
  - VDS
- Division: TOYOTA (Dropdown)
- Model: Tundra (Dropdown)
- Year: 2015 (Dropdown)
- Buttons: Clear, Search

The 'Reference Documents' section lists several documents, including 'Multimedia Software Download Instructions', 'Safety Recall A0G - 2003 Sequoia - Skid Control ECU Update', and 'Toyota ECU Flash Reprogramming Bulletin T-SB-0012-13'.

Below the search form is a table with the following columns: 'Current ECU CAL ID', 'New ECU CAL ID', 'Document Title (Release Date)', 'Year / Model / VDS', and 'Market'. A red arrow points to the document title 'Toyota 2014 - 2015 Tundra Supercharger Fit Kit PTR29-34140 (Fit Kit) Rev. D (2015-02-10)'.

Current ECU CAL ID	New ECU CAL ID	Document Title (Release Date)	Year / Model / VDS	Market
30CL0000			2015 / Tundra / AHSF1	
30CL0100			2015 / Tundra / AYSF1	
30CL0200			2015 / Tundra / BWSF1	
3YWF7800			2015 / Tundra / BVSF1	
3YWF9200			2015 / Tundra / CWSF1	
3YWF9600			2015 / Tundra / CVSF1	
30CL0001			2015 / Tundra / DMSF1	
30CL0101			2015 / Tundra / DWSF1	
30CL0201			2015 / Tundra / DVSF1	
3YWF7801			2015 / Tundra / EMSF1	
3YWF9201	3YWF9800	Toyota 2014 - 2015 Tundra Supercharger Fit Kit PTR29-34140 (Fit Kit) Rev. D (2015-02-10)	2015 / Tundra / EYSF1	USA
3YWF9601	3YWF9801		2015 / Tundra / FVSF1	
30CL1000	3YWF9900		2015 / Tundra / GVSF1	
30CL1100	3YWF9901		2015 / Tundra / HVSF1	
30CL1200			2015 / Tundra / NUSF1	
3YWF7900			2015 / Tundra / NYSF1	
3YWF9300			2015 / Tundra / PVSF1	
3YWF9300			2015 / Tundra / PWSF1	
30CL1001			2015 / Tundra / RVSF1	
30CL1101			2015 / Tundra / RUSF1	

# Techstream ECU Flash Reprogramming Procedure

## Operation Procedure (Continued)

2. Connect the GR8 Battery Diagnostic Station.

**NOTE**

Refer to [Vehicle Reprogramming Tips](#) for other approved Chargers, located on TIS, *Diagnostics – Calibrations – Reference Documents*.


A. Connect the GR8 Battery Diagnostic Station to the vehicle and turn it ON.

B. Select Power Supply Mode by following the screen flow below.

**NOTICE**

- ECU damage may occur if the correct battery charger and mode setting are NOT used.
- Power Supply Mode is used to maintain battery voltage at 13.5 volts while flash reprogramming the vehicle.
- For details on how to use the GR8 Battery Diagnostic Station, refer to the [GR8 Instruction Manual](#) located on TIS, *Diagnostics – Tools & Equipment – Battery Diagnostics*.

Figure 7.



## Techstream ECU Flash Reprogramming Procedure

### Operation Procedure (Continued)

3. Click the appropriate calibration ID and reprogram the vehicle's ECU with Techstream.
  - A. After reviewing the procedures outlined in the selected Service Bulletin, click the appropriate calibration ID link by matching the vehicle's current calibration ID to the Previous Calibration ID in the Calibration Identification Chart.

**NOTE**

- Calibration files are embedded as live links in the Service Bulletin.
- Some vehicles require special preparation — please review the selected Service Bulletin carefully.

Figure 8. New Image in Process

ECM CALIBRATION: SHIFT FEELING ENHANCEMENT – TC007-03 Revised						November 7, 2003
Calibration Identification Chart	MODEL YEAR	MODEL	ECM (CPU)	PREVIOUS CALIBRATION ID	NEW CALIBRATION ID	VDS
	2004 & 2005	2WD	Main	30801000	30801100 30801200 30801300 30804000	<a href="#">30806000</a>
50801000 50801100 50803000				<a href="#">50805000</a>		
4WD		Main	30802000 30802100 30802200 30802300 30805000	<a href="#">30807000</a>	BA22C BA23C	
			50802000 50802100 50804000			<a href="#">50806000</a>

## Techstream ECU Flash Reprogramming Procedure


### Operation Procedure (Continued)

- B. Click *Open* to load calibration file information.

Figure 9.

#### NOTE

Techstream pulls calibration files as needed to ensure the latest calibration file is used. Do NOT save calibrations locally on the hard drive or other media.



#### NOTICE

Errors during the flash reprogramming process can permanently damage the vehicle ECU. Minimize the risk by following the steps below.


- Battery voltage **MUST NOT FALL BELOW 11.8 volts** during reprogramming. Confirm battery voltage is higher than 11.8 volts, but be sure voltage **DOES NOT RISE ABOVE 16.0 volts** during reprogramming.
- Turn OFF all vehicle accessories (e.g. audio system, A/C, interior lights, DRL, etc.). Do NOT add to or significantly change the vehicle's electrical load while reprogramming.
- Confirm the hood is open and ensure under hood temperature does NOT exceed 158°F (70°C).
- Confirm cable connections between the vehicle and Techstream are secure.
- Do NOT disconnect or turn off Techstream or vehicle ignition during reprogramming.
- Set parking brake.
- Complete ALL flash calibration updates provided for each ECU.
- If the battery's state of charge or capacity are in question, test with SST. No. [00002-V8150-KIT](#) "Digital Battery Analyzer," and follow Service Bulletin No. [PG001-06](#), "Battery Maintenance for In-Stock Vehicles & Pre-Delivery", or the appropriate "Maintenance for HV & Auxiliary Batteries" Service Bulletin.
- The GR8 Battery Diagnostic Station MUST be used in Power Supply Mode to maintain battery voltage at 13.5 volts while flash reprogramming the vehicle. For details on how to use the GR8 Battery Diagnostic Station, refer to the [GR8 Instruction Manual](#) located on TIS, *Diagnostics – Tools & Equipment – Battery Diagnostics*.

# Techstream ECU Flash Reprogramming Procedure

## Operation Procedure (Continued)

- C. Click *Next* to start the calibration update process.

Figure 10.




- D. Confirm the following:

- PC is connected to VIM.
- VIM is connected to DLC3 connector.
- Ignition is ON and engine is OFF or “READY” OFF (hybrid vehicles).

Then click *Next*.

Figure 11. Using Techstream 2.0 or Techstream Lite



<b>1</b>	Select Correct Device Tool (“Mongoose MFC,” “MongoosePro MFC,” or “MongoosePro MFC2” [green])
----------	---

## Techstream ECU Flash Reprogramming Procedure

### Operation Procedure (Continued)

E. Verify correct current calibration and new calibration information. Then click *Next*.

**NOTE**

- The total number of calibration IDs in the calibration file corresponds to the number of reprogrammable processors in the ECU.
- Each calibration file may contain up to three separate calibrations.
- Figure 12 shows an example of the update procedure for a two-processor ECU.

Figure 12.

Calibration Update Wizard - Screen S701-09

### Calibration Selection Confirmation

ENG & ECT

Current Calibration:

Current Cal ID	50C80000
Current Cal ID	30CL0000
Current Cal ID	

New Calibration Information:

New Cal ID	50C80100
New Cal ID	30CL0200
New Cal ID	
Issue Date	Oct. 06, 2014
Model Name	Tundra
Year	14 - 15
Engine Type	3UR-FE
Vehicle Type	2WD

✓ Selected Calibration file is authorized to update this vehicle.  
Press NEXT to continue.

NOTE: Refer the applicable TSB for calibration file information.

Select New Cal    Next    Cancel


## Techstream ECU Flash Reprogramming Procedure

---

### Operation Procedure (Continued)

F. Turn ignition OFF. Then click *Next*.

Figure 13.



## Techstream ECU Flash Reprogramming Procedure

### Operation Procedure (Continued)

G. Confirm the following:


- Ignition is ON and engine is OFF or “READY” OFF (hybrid vehicles).
- Hood is open.
- All accessories are OFF.
- Battery voltage is above 11.8 volts.

**NOTICE**

Verify the vehicle is connected to a battery charger before continuing — If battery voltage falls below 11.8 volts, ECU damage may occur.

Then click *Start*.

Figure 14.



**NOTE**

If key cycle is NOT done properly, reprogramming will stop at 10% and Cal 1 will fail to load.

## Techstream ECU Flash Reprogramming Procedure

---


### Operation Procedure (Continued)

H. Do NOT disturb the vehicle during flash reprogramming.

**NOTE**

- ECU flash reprogramming may take anywhere from 3 – 30 minutes per calibration file.
- Reprogramming time will vary depending on model and ECU communication protocol. Vehicles using CAN communication protocol will reprogram much faster (2 – 7 minutes).

Figure 15.



**NOTE**

- If vehicle requires only ONE calibration update, then proceed to step N in this bulletin.
- If vehicle requires a SECOND calibration update, then continue as follows:
  - For serial communication vehicles, go to step I.
  - For CAN communication vehicles, go to step K.


## Techstream ECU Flash Reprogramming Procedure

---

### Operation Procedure (Continued)

- I. When Cal 1 has completed the update process, turn ignition OFF for a minimum of 10 seconds. Then click *Next*.

Figure 16.




## Techstream ECU Flash Reprogramming Procedure

### Operation Procedure (Continued)

J. Turn ignition to the ON position. Then click *Start*.

Figure 17.



**NOTE**

If key cycle is NOT done properly, reprogramming will stop at 10% and Cal 2 will fail to load.


## Techstream ECU Flash Reprogramming Procedure

---

### Operation Procedure (Continued)

K. Do NOT disturb the vehicle during flash reprogramming.

Figure 18.




## Techstream ECU Flash Reprogramming Procedure

---

### Operation Procedure (Continued)

- L. Turn ignition OFF for a minimum of 10 seconds. Then click *Next*.

Figure 19.




## Techstream ECU Flash Reprogramming Procedure

---

### Operation Procedure (Continued)

M. Turn ignition to the ON position. Then click *Next*.

Figure 20.




## Techstream ECU Flash Reprogramming Procedure

### Operation Procedure (Continued)

N. Confirm all calibrations were updated as specified in the Service Bulletin. Then click *Finish*.

Figure 21.



**NOTE**

On some models, DTCs may set as a result of reprogramming. If DTCs are present, clear codes and run the Health Check again. Troubleshoot any remaining Current, Pending, or History codes. Permanent codes will not be cleared using Techstream. Permanent codes do not illuminate the MIL and do not require troubleshooting. They will clear during normal driving once the Universal Trip Drive Pattern is performed.

## Techstream ECU Flash Reprogramming Procedure

### Operation Procedure (Continued)

4. Attach the Authorized Modifications Label.

A. Using a permanent marker or ball point pen, complete the Authorized Modifications Label and attach to the vehicle. The Authorized Modifications Label is available through the MDC, P/N 00451-00001-LBL.

**Figure 22.**

<b>TOYOTA MOTOR CORPORATION</b>	
<b>AUTHORIZED MODIFICATIONS</b>	
THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:	
① →	<i>89661-08120</i>
② →	<i>30806000, 50805000</i>
THESE MODIFICATIONS HAVE BEEN APPROVED AS APPROPRIATE BY EPA AND CARB	
③ →	DEALER CODE: <i>31301</i> DATE: <i>8/2/06</i> ← ④
	CHANGE AUTHORITY: <i>TSB TC007-03</i> ← ⑤

<b>1</b>	<b>Replacement ECU Part Number</b>
<b>2</b>	<b>Calibration ID(s)</b>
<b>3</b>	<b>Dealer Code</b>

<b>4</b>	<b>Date Completed</b>
<b>5</b>	<b>Service Bulletin or Campaign Number</b>

B. Attach the label under the hood in the location determined by the specific Service Bulletin or Campaign.

**NOTE**  
Wait 60 – 90 seconds for ink to set before handling.