



# Service Bulletin

## TECHNICAL

**Subject:** Wobble Felt During Light Acceleration Between 19 km/h (12 mph) to 24 km/h (15 mph)

**Attention:** This Bulletin also applies to vehicles sold in Mexico.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Verano	2012	2016			All	All

<b>Condition</b>	Some customers may comment on a wobble felt during light acceleration between 19 km/h (12 mph) to 24 km/h (15 mph).
<b>Cause</b>	This condition may be due to generated axial force from the axle angle causing the powertrain to move side to side.

### Correction

If you encounter a vehicle with the above concern, replace both the front wheel drive shafts and all one time use fasteners as required. Refer to *Front Wheel Drive Shaft Replacement - Left/Right Side* in SI.

### Parts Information

Description	Part Number
SHAFT ASM-FRT WHL DRV	13335138
SHAFT ASM-FRT WHL DRV	13335139
One Time Use Fasteners	Refer to Parts Catalog

### Warranty Information

Labor Operation	Description	Labor Time
3080158*	Both Front Wheel Drive Shafts Replacement	1.1 hrs
Add	Transmission Fluid Drain and Fill	0.7 hr

\*This is a unique Labor Operation for Bulletin use only.

<b>Version</b>	2
<b>Modified</b>	March 14, 2016 — Updated Correction, Parts Information and Warranty Information.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION