



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Stop/Start System is Inoperable After a System Repair and No DIC Message or DTC is Set

**Models:** 2016 Cadillac ATS, CTS  
Equipped with Stop/Start System (RPO KL9)

**Attention:** This PI also applies to any of the above models that may be Export vehicles.

### Condition/Concern

Some technicians may notice that the Stop/Start System is inoperable after a stop/start system repair or after any repair where the 12V battery negative cable has been disconnected. No DIC message or DTC will be set.

### Recommendation/Instructions

The learn procedure needs to be completed on the Battery Sensor Module. It will be necessary to park the vehicle for 3 hours without being driven to allow the learn procedure to be completed on the Battery Sensor Module.

If the repair is a non-Stop/Start repair and the vehicle is being returned to the customer, advise the customer that the vehicle will not Stop/Start until the vehicle has sat for 3 hours undisturbed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION