

**NUMBER:** 08-001-15

**GROUP:** Electrical

**DATE:** January 08, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

### SUBJECT:

L25 Interim Repair Procedure Brazil ONLY

## **OVERVIEW:**

Upon starting the vehicle the Frequency Operated Button Ignition Key (FOBIK), may not fully seat in the "ON" position. If not fully seated, under certain operating conditions (for example bumpy roads) the FOBIK could inadvertently move to the "Accessory" mode. This could cause unintended engine shut off and the passive restraint systems, including the airbags to shut off. This could increase the risk of a crash under certain driving conditions and increase the risk of occupant injury during a crash.

Chrysler intends to repair the vehicle free of charge (parts and labor). However, the part required to provide a permanent remedy for this condition is currently not available.

NOTE: Chrysler is making every effort to provide the part as guickly as possible.

## **MODELS:**

2008- 2010 (RT)		Chrysler Town & Country (Brazil only)	
2009- 2010	(LX)	Chrysler 300 (Brazil only)	

NOTE: This bulletin applies to vehicles in Brazil with Brazil Country Code (sales Code 8A1).

NOTE: This bulletin will be cancelled when parts become available.

#### **REPAIR PROCEDURE:**

1. Remove all objects from the FOBIK (such as additional keys, key chains, etc.)

NOTE: Ensure that the FOBIK is securely and correctly aligned in the "On" position and not aligned between the "On" and "Accessory" position before driving the vehicle.

08-001-15 -2-

# **POLICY:**

Reimbursable within the provisions of the warranty.

# TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-80-32-95	L25 Interim Ignition Key Obstruction	6 - Electrical and Body Systems	0.2 Hrs.

# FAILURE CODE:

ZZ Service Action	
-------------------	--