



NUMBER: 08-006-15

GROUP: Electrical

DATE: January 22, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-005 ONLY APPLICABLE TO VEHICLES PRODUCED FOR THE CANADIAN MARKET. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING "HELP" THEN "HELP CONTENTS" AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE LEVEL MUST BE AT 15.02 OR HIGHER TO PERFORM THIS PROCEDURE.

SUBJECT:

Flash: Incorrect Language Displayed In The Cluster

OVERVIEW:

This bulletin involves reprogramming the Instrument Panel Cluster (IPC) with updated software.

MODELS:

2014	(DS)	Ram 1500 Pickup
2014	(DJ)	Ram 2500 Pickup
2014	(D2)	Ram 3500 Pickup
2014	(DD)	Ram 3500 Cab Chassis
2014	(DP)	Ram 4500/5500 Cab Chassis
2014	(DX)	Ram Truck (Mexico)

NOTE: This bulletin applies to vehicles built on or after April 11, 2014 (MDH 0411XX) on or before May 21, 2014 (MDH 0521XX) equipped with Uconnect 3.0 AM/FM (sales code RA1) or Radio Delete (sales code RA8) with Instrument Cluster W/Display Screen (sales code JAT) or Instrument Cluster (sales code JA4).

SYMPTOM/CONDITION:

The customer may notice when trying to switch the language from English to Spanish/French, only the radio will display the correct language. The cluster will still display English.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify no DTCs are set. If DTCs are present record them on the repair order and repair as necessary before proceeding further with this bulletin.

If a Canadian customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describes the symptom/condition, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the IPC with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the "HELP" tab on the upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.

NOTE: If the IPC has the latest software in it and no updates are available, use LOP 18-19-47-94 to close this active RRT.

2. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow the tech to clear them.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-47-94	Module, Instrument Panel Cluster (IPC) - Inspect and/or Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 4 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

FM	Flash Module
----	--------------