

Service Category	Brake			Lexus Supports
Section	Brake (front)	Market	USA	ASE Certification

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2007 – 2015	LS460	

REVISION NOTICE

December 4, 2015 Rev1:

• The Parts Information section and Repair Procedure section has been updated.

Any previous printed versions of this bulletin should be discarded.

Introduction

Some 2007 – 2015 model year 2WD LS 460 standard (non F-Sport, non AWD) and LS 460L vehicles may exhibit vibration/pulsation in the brake pedal and/or steering wheel while lightly applying the brake pedal at high speeds (65 – 75 mph). Follow the procedures in this bulletin to address this condition.

Warranty Information

OP CODE	DESCRIPTION	TIME*	OFP	T1	T2
BR1501	Front Caliper Modification and Front Disc Brake Repair (One Side)	0.7	04947-50120	OP	10
BR1501A	Front Caliper Modification and Front Disc Brake Repair (Opposite Side)	0.5	43512-50240	90	13

* Time includes BOTH (1) caliper modification, and (2) rotor resurfacing OR rotor replacement.

APPLICABLE WARRANTY

- This repair is covered under the Lexus Basic Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.



Parts Information

PART NUMBER	PART NAME	QTY
47748-50200	Spring, Anti-rattle	2

Order the Following Parts ONLY if Needed:

DRIVETRAIN	PART NUMBER	PART NAME	QTY
2WD	43512-50240	Disc, FR	2
-	04465-50260	Pad Kit, Disc Brake, Front	1

Repair Procedure

1. Conduct a road test to verify the condition described in the Introduction.

Rev1

NOTE

The condition usually occurs when the vehicle is driven at high speeds (60 - 75 mph) and when braking at low pressure.

Can the vibration condition be duplicated?

- **YES** Continue to step 2.
- NO This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
- 2. Remove the front wheel.
- 3. Measure front rotor thickness and refinish or replace as necessary.
 - A. Measure the front rotor thickness. If the thickness is below the standard specification, replace the front rotors.

DISC SIZE	STANDARD THICKNESS	MINIMUM THICKNESS	
13.14 inch	30.0 mm (1.181 in.)	27.0 mm (1.063 in.)	

- B. If the front rotor thickness is within specification, resurface the rotors to a smooth finish using an on-car brake lathe.
- 4. Inspect the front brake pads.

Measure the thickness of both front brake pads. If the thickness is out of specification, replace the front brake pads.

Standard Thickness: 13.5 mm (0.532 in.) Minimum Thickness: 1.0 mm (0.039 in.)

NOTE

If the thickness is within specification, there is no need to replace the brake pads.



Rev1

Front Brake Vibration

Repair Procedure (Continued)

5. Install the additional M-Spring.

HINT

M-Spring shown at right.

Figure 1. M-Spring/Anti-Rattle Spring (P/N 47748-50200)



A. Remove all components from the calipers (including brake pads and all fitting kit components). Figure 2.



NOTE

Check brake pad surface. If there is any abnormal surface condition, such as wear or streak marks, replace the brake pads.



Repair Procedure (Continued)

B. Install the outer brake pad (with new or original pads).

Figure 3.



C. Install the inner brake pad.







Repair Procedure (Continued)

D. Temporarily install the slide pin on the trailing side of the caliper to secure the brake pads.

Figure 5.



Figure 6.



E. Reinstall the original M-Spring onto the leading side of the caliper.



Repair Procedure (Continued)

F. Insert the slide pin on the leading side through the M-Spring.

NOTE

Make sure that the slide pin is inserted through the spring.

Figure 7.





Rev1

Front Brake Vibration

Repair Procedure (Continued)

G. Remove the trailing side slide pin that was previously inserted to secure the brake pads. The leading side installation is now complete.



Figure 8.





Repair Procedure (Continued)

H. Install the NEW M-Spring onto the trailing side of the caliper.

Figure 9.



I. Insert the trailing side slide pin through the M-Spring. The dual M-Spring installation is now complete.

Figure 10.





Repair Procedure (Continued)

J. Install the original pad wear indicator retainer.

Rev1

Figure 11.



K. Install the original anti-rattle spring.







Rev1

Front Brake Vibration

Repair Procedure (Continued)

L. Repeat the steps on the opposite side.

Figure 13.



6. Reinstall the front wheel and torque to specification using the correct tightening sequence shown in Figure 14.

CAUTION

It is ESSENTIAL to install the front wheel lug nuts with the correct torque specification using a torque wrench, in the correct star pattern sequence (shown in Figure 14).

NOTICE

Do NOT use an impact gun to tighten the lug nuts.

Torque: 140 N*m (1428 kgf*cm, 103 ft*lbf)

Figure 14. Star Pattern Sequence



7. Road test to confirm vibration/pulsation condition has been remedied.