



NUMBER: 18-002-15 REV. A
GROUP: Vehicle Performance
DATE: November 04, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 18-002-15, DATED JANUARY 07, 2015, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDE ADDITIONAL MODELS, UPDATED SYMPTOMS/CONDITIONS, REVISED BUILD DATES AND UPDATED FAILURE CODES.**

HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING “HELP” THEN “HELP CONTENTS” AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

****THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.****

SUBJECT:
Flash: Diagnostic And System Enhancements

OVERVIEW:
This bulletin involves reprogramming the Powertrain Control Module (PCM) with updated software.

MODELS:

2015	(DJ)	Ram 2500 Pickup
2015	(D2)	Ram 3500 Pickup
2015	(DD)	Ram 3500 Cab Chassis
2015	(DP)	Ram 4500/5500 Cab Chassis

NOTE: **This bulletin applies to vehicles equipped with 6.4 Engine (Sales Code ESA or ESB) and 6-Speed Auto Aisin AS66RC transmission or 6-Speed Automatic 66RFE transmission (Sales Code DFP or DF3).**

SYMPTOM/CONDITION:

During normal diagnostics a technician may find one or more of the following Diagnostic Trouble Codes (DTCs) present:

- **P3426 - Cylinder 4 Deactivation Control Performance.
- P3402 - Cylinder 1 Deactivation Control Performance.
- P3442 - Cylinder 6 Deactivation Control Performance.
- P3450 - Cylinder 7 Deactivation Control Performance.**
- U0140 - Lost Communication With Body Control Module. (Attempting to clear this DTC will be unsuccessful.)
- P030X - Cylinder X Misfire Detected.
- P0300 - Multiple Cylinder Misfire Detected.

Additionally the following enhancements have been implemented:

- **Improved Cruise Control Acceleration mode.
- Improved Multi Displacement System operation. **6-Speed Automatic 66RFE transmission (Sales Code DFP).**
- Multi Displacement System function improved while in stationary mode. **6-Speed Auto Aisin AS66RC transmission (Sales Code DF3).****
- Potential small improvement in fuel economy at higher altitudes.
- Potential improvement in high altitude engine idle RPM stability.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all engine systems are functioning as designed. If DTCs and/or symptom/conditions other than the ones listed above are present, record them on the repair order and repair as necessary before proceeding further with this bulletin.

If the technician finds any of the DTCs and/or symptom/conditions listed above, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the "HELP" tab on the upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.
2. Clear any DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow the DTCs to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation	Description	Skill Category	Amount
-----------------	-------------	----------------	--------

No:			
18-19-06-FF	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	8 - Engine Performance	0.2 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 5 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must choose which failure code to use. If the customer came in with an issue and if the dealer finds a software update to correct that issue, use failure code CC, for all other use failure code RF.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash