

10/7/15

15 KL

GPOP - Issue Review System

Part Number: 5XN09DX9A\$, 5XN09HL1A\$, 5XN17DX9A\$, 5XN17HL1A\$, 5XN13DX9A\$, 5XN13HL1A\$, 5VF79DX9A\$, 5VF79HL1A\$, 5VF79LU5A\$, 5VG18DX9A\$, 5VG18LU5A\$, 5VH20DX9A\$, 5VH20LU5A\$, 5RA14DX9A\$, 5RA14LU5A\$, 5RA19DX9A\$, 5RA19LU5A\$, 5VF75DX9A\$, 5VF78DX9A\$, 5XM91DX9A\$, 5XM91LU5A\$, 5XM92DX9A\$, 5XM92LU5A\$, 5VF59DX9A\$, 5VF62DX9A\$, 5VF63DX9A\$

Part Description: Front seat trim covers

Issue Description: For vehicles built prior to 7/13/2015, if the customer complaint is related to a hard spot or wear mark at the rear/center location of the front seat cushion cover, replace the heated seat element with a minimum AE level part. Remove adhered element with care to avoid damage to cushion foam pad. If replacement of the passenger cushion foam pad is necessary, The Occupant Detection System (ODS) module and foam pad must be ordered and replaced as a paired assembly. Not to be replaced independently.

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.