

NUMBER: 23-019-15

GROUP: Body

DATE: May 22, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-056. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Discolored Door Hinge Nuts

OVERVIEW:

This bulletin involves replacing all the lower nuts on the side upper and lower door hinges.

MODELS:

2015 (JK) Jeep Wrangler

NOTE: This bulletin applies to vehicles built on or after May 06, 2015 (MDH 0506XX) and on or before May 07, 2015 (MDH 0507XX).

SYMPTOM/CONDITION:

The customer may describe discoloring or rust from the lower nut securing the doors to the hinges.

23-019-15 -2-

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair on all side doors.

Some lower nuts for the side door hinges may have been installed without the plating (1) process to the nut, **New plated nuts (2) will have a slight shine or low gloss** (Fig. 1).



Fig. 1 Door Hinge Nuts

- 1 Non Plated Nut
- 2 Plated Nut

PARTS REQUIRED:

Qty.	Part No.	Description
(AR)	06511744AA	nut, door hinge

-3- 23-019-15

REPAIR PROCEDURE:

REMOVAL

1. Remove the door hinge lower nuts (one hinge at a time only) and discard the nut (Fig. 2).



Fig. 2 Door Hinge Nut Location

2. Install the new nut for each hinge and tighten to 8.5 N·m (75 in. lbs.).

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-40-15-90	Nut, Lower Door Hinge - Replace All (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------