

SB-10056886-9852



Countries:	CANADA, TAIWAN, UNITED STATES, GUAM, KOREA, SOUTH KOREA	Document ID:	IK0300061
Availability:	ISIS, Bus ISIS, FleetISIS	Revision:	2
Major System:	SPRINGS AND SUSPENSION	Created:	8/27/2014
Current Language:	English	Last Modified:	5/13/2015
Other Languages:	NONE	Author:	Matthew Boyer
Viewed:	811		

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 12	Not Helpful 2
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	--------------------------	-----------------------------

Title: 8,000 LBS Front Suspension Lean Correction**Applies To: TerraStar, DuraStar and AE Bus**

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

5/13/2015 - Added link to article for Spacer Part Numbers.
 8/21/2014 - Initial Article Release
 02/19/2015 - Updated U-bolt part number to be a 1/2" longer bolt

Description

Certain TerraStar, DuraStar, and AE Bus models built with a 8,000 LBS front suspension, may experience a chassis lean causing the left front(driver side front) of the vehicle to be lower than the right front(passenger side front). This is caused by a stack up of different component locations on the truck, which cause a weight bias to one side. When this condition is present on a truck equipped with IROS rear air ride suspension, the right rear can be higher than the left rear.

- Replacing a leaf spring for a TerraStar, DuraStar, or AE bus will not correct a lean condition where the left front is lower than the right front.

Inspection


1. Park the truck on flat, level ground
2. Using a tape measure, measure the front of the truck from the frame rail to the ground
3. If the left front is lower than the right front by a measurement that is greater than 3/8", then a spacer needs to be installed

Spacer Installation

1. Block the wheels of the truck with wheel chocks
2. Jack up the front of the truck, and support the chassis with jack stands placed under the frame rails
3. Using a floor jack, support the front axle to keep it from falling once the U-Bolts have been removed
4. Remove the U-Bolts
5. Lower the jack to create enough space between the spring and the axle to insert the spacer
6. Insert the spacer with the tab pointed down. Ensure that the lower tab fits into the hole in the axle, and the center pin tab of the spring fits into the spacer. Raise the floor jack to take up all space between the spacer, the axle, and the spring
7. Install the new U-Bolts. In a diagonal pattern, torque the U-Bolts in 50 FT-LBS increments

8. Torque U-Bolts to a final torque value of 260 FT-LBS to 300 FT-LBS(192 N·M to 222 N·M)

Parts Information



Spacer 2512808C1

Refer to [IK1400023](#) for Spacer Part Numbers.

Part Number	Description	Quantity Needed
2512808C1	Spacer- 3" wide by 1/2" Thick	1
3609927C1	New U-Bolts- 1/2 inch longer	2
416743C1	Nuts for U-Bolts	4

Labor Information

Operation	Description	Hours	Group	Noun
A03-200	Install Front Spring Spacer	0.7	03000	523

Hide Details

Feedback Information

Viewed: 810
 Helpful: 12
 Not Helpful: 2

Staff ID	Client ID	Comments	Created Date
	DY02680	You received the following feedback From: dy02680 - Bill Knoth Email Address: bknoth@tristateinternational.net Job Classification: SE008, Service Technician Dealer: TRI-STATE INT'L TRKS Feedback: This article (IK0300061) only says it applies to 8,000lb front axles, however in IK1400023 it states to follow this article(IK0300061) with 8,000lb OR LESS front axles. I had a terrastar with a 7,000lb front axle and had to made a tech case to determine if this article applies, do to the inconsistencies between the two articles. A little more clarification in this article would be nice. Thank you. (also you have a miss print in the link to the article IK1400023)	5/13/2015 4:43:10 PM