NISSAN NORTH AMERICA, INC



Technical Bulletin

SERVICE BULLETIN Reference: Date:			
Classification:	Reference:	Date:	
BT15-011	NTB15-039	April 27, 2015	

2015 MURANO; FRONT DOOR WILL NOT OPEN WITH OUTSIDE HANDLE

APPLIED VEHICLE: 2015 Murano (Z52)

IF YOU CONFIRM:

Or the customer reports, one or both front doors will not open with the outside handle under the following conditions:

 After attempting to unlock the doors with the Intelligent Key, key fob, and mechanical key,

AND

• The vehicle has been in below freezing temperatures for an extended period,

AND

 Door(s) open normally after the vehicle has warmed (vehicle left in the sun, moved indoors, or driven for several minutes).

ACTION:

- 1. Check the condition of the foam in the front door outside molding of the door that would not open (see Figure 1, 2 and 3 on the next page).
- 2. If the foam does not fit properly (as shown on the next page), replace the front door outside molding.
 - Refer to the Electronic Service Manual (ESM), section EXT Exterior, for front door outside molding replacement.

NOTE: Do <u>not</u> replace a front door lock (latch assembly) if the front door opens normally after the vehicle has warmed as described above.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.




Figure 1




Figure 2 Figure 3

2/3 NTB15-039

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QTY
MOLDING ASSY-FRONT DOOR OUTSIDE, LH (Front Door Outside Molding, LH)	80821-5BC0A	1; if needed
MOLDING ASSY-FRONT DOOR OUTSIDE, RH (Front Door Outside Molding, RH)	80820-5BC0A	1; if needed

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace One Molding	(1)	UH16AA	ZE	32	(1)

- (1) Refer to the Parts Table and use the appropriate part number as the PFP.
- (2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated flat rate time.

3/3 NTB15-039