



Technical Bulletin

SB-10058370-4020

SERVICE BULLETIN

FA15-003

NTB15-062

Date: July 15, 2015

2014-2015 ROGUE; POPPING NOISE FROM FRONT SUSPENSION WHEN TURNING

APPLIED VEHICLE: 2014-2015 Rogue (T32)

IF YOU CONFIRM

There is a popping noise from either the right or the left front coil springs when turning to the right or left.

NOTE: Electronic chassis ears may be helpful in isolating this type of noise.

ACTION

Replace both the front left and front right coil springs, front strut bearings and single use nuts (Figure 1) with those listed in the Parts Information table on the next page.

NOTE: Refer to the Electronic Service Manual (ESM), section **FSU – Front Suspension**, for further information.

IMPORTANT: The parts listed in this bulletin are specific to the Applied Vehicle and <u>cannot be used</u> on early models or Rogue Select.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.




Figure 1

PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
Front Coil Spring (FWD vehicles)	54010-9TA0A	2
Front Coil Spring (AWD vehicles)	54010-9TA1A	2
Strut mount bearing	54325-8271R	2
Steering Knuckle Nut	01223-N2011	2
Strut Top Nut	54588-JA005	2
Stabilizer Connecting Rod Nut	04000-JAUU0	2

CLAIMS INFORMATION

Submit a Primary Failed Part (PP) type line claim using the following claims coding:

DESCRIPTION	OP CODE	PFP	SYM	DIA	FRT
Install Both Coil Springs with Strut Bearings	MA15AA	(1)	BC	32	(2)
	MA153A				

(1) Reference the Parts Information Table and use the applicable Front Coil Spring part number (54010-****) as the PFP.

(2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated FRT.