

**NUMBER:** 18-071-15**GROUP:** Vehicle Performance**DATE:** October 06, 2015

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THIS BULLETIN SUPERSEDES SERVICE BULLETIN 18-009-14, DATED FEBRUARY 15, 2014, WHICH SHOULD BE REMOVED FROM YOUR FILES. THIS IS A COMPLETE REVISION AND NO ASTERISKS HAVE BEEN USED TO HIGHLIGHT REVISIONS.**

**SUBJECT:**

Unable to Program Keys After Wireless Ignition Node Replacement

**MODELS:**

2014	(RT)	Town & Country/Grand Caravan
2014	(JS)	200/Avenger

**NOTE: This bulletin applies to RT vehicles equipped with a 3.6L engine (sales code ERB) built on or before November 21, 2013 (MDH 1121XX) and JS vehicles equipped with a 3.6L engine (sales code ERB) or a 2.4L engine (sales code ED3 or EDG) built on or before January 16, 2014 (MDH 0116XX).**

**DISCUSSION:**

Technicians may find that the original vehicle keys/FOBIKs do not function properly following replacement of the Wireless Ignition Node (WIN/WCM). The Secret Key information stored in the PCM may be corrupt. The Powertrain Control Module must be updated to the latest available software to allow the PCM to properly store/transfer valid secret key information. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the PCM software.

**NOTE: If the WIN had been replaced prior to this software update, the original keys/FOBIKs will need to be replaced.**

**NOTE: Perform the "PCM Replaced" function located in wiTECH under the WCM/WIN module view under the Miscellaneous Functions tab. This will transfer the current/valid Secret Key information from the WIN/WCM to the PCM.**

**POLICY:**

Information Only.