

Bulletin No.: PIP5074B

Date: 04-Nov-2015

# Service Bulletin

## INFORMATION

Subject: Oil Filter Contact With A/C Compressor Hose

Models: 2012-2013 Chevrolet Captiva Sport

with 3.0L Engine (RPO LFW)

This PI was superseded to update Recommendation/Instructions. Please discard PIP5074A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

#### Condition/Concern

Oil leak from the oil filter due to filter rubbing on the A/C compressor hose after an oil change using a PF63 oil filter.

#### Recommendation/Instructions

If this condition is encountered, use PF64 oil filter for replacement and during all subsequent oil changes.

Further this oil filter should now be in the Electronic Parts Catalog as the recommended oil filter for 2012 and 2013 Captiva Sport equipped with a 3.0 LFW engine.

A new A/C compressor hose has been developed to create the proper clearance and was put into production vehicles in December of 2012.

The new A/C hose part # is 25928177 and should be on all of these vehicles built after 1/2/2013.

Engineering has determined that this oil filter will offer the same protection to the engine as the PF63 so the previous hose P/N 22759948 does not need to be replaced for this concern.

### **Warranty Information**

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4065530	Oil Filter Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

