



Program Bulletin

CUSTOMER SATISFACTION PROGRAM

SUBJECT: Water Leak onto the Left Cabin Floor

MODELS: 2016 Chevrolet Colorado
2016 GMC Canyon

.....
THIS PROGRAM IS IN EFFECT UNTIL NOVEMBER 30, 2017.
.....

CONDITION

Certain 2016 model year Chevrolet Colorado and GMC Canyon model vehicles may have a condition in which an improperly sealed vertical seam near the driver's side dash may cause water to leak onto the driver side cabin floor. This can result in wet carpets or a mildew smell.

CORRECTION

Dealers are to seal the vertical seam near the driver's side dash.

VEHICLES INVOLVED

All involved vehicles are identified by Vehicle Identification Number on the Investigate Vehicle History screen in GM Global Warranty Management system. Dealership service personnel should always check this site to confirm vehicle involvement prior to beginning any required inspections and/or repairs. It is important to routinely use this tool to verify eligibility because not all similar vehicles may be involved regardless of description or option content.

For dealers with involved vehicles, a listing with involved vehicles containing the complete vehicle identification number, customer name, and address information has been prepared and will be provided to US and Canadian dealers through the GM GlobalConnect Recall Reports, or sent directly to export dealers. Dealers will not have a report available if they have no involved vehicles currently assigned.

The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this program is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this program.

PART INFORMATION


The sealer required to complete this program is to be obtained from Kent Automotive at 1-800-563-1717 (Canada or US) or www.kent-automotive.com (US Only). **Do not order from GMCC&A.**

Part Number	Description	Quantity/Vehicle
P10200* (Obtain from Kent Automotive)	Clear Seam Sealer (one 5 oz. tube will service 4 vehicles)	As Required (Submit in Net Item)


SERVICE PROCEDURE

Note: The following repair steps involve resealing the cowl/plenum area and the driver side hinge pillar. When sealing these areas, inspect the surrounding body seam sealer for voids, gaps, or missing material. Reseal all seams as required.

1. Open the hood and install fender covers.
2. Remove the windshield wiper motor. Refer to *Windshield Wiper Motor Replacement* in SI.
3. If required, clean any dirt or loose debris from the seam to be sealed.
4. Using a general purpose adhesive cleaner, clean the area to be sealed.



4310928



4310932

5. Apply seam sealer to the above (1) and the below (2) seams as shown above.

6. Partially remove the front wheelhouse liner. Refer to *Front Wheelhouse Liner Replacement* in SI.



4310933

7. If required, clean any dirt or loose debris from the seam to be sealed.
8. Using a general purpose adhesive cleaner, clean the area to be sealed.
9. Apply seam sealer to the seam as shown above.
10. Allow the sealer to cure per the manufacturer’s instructions.
11. Install the front wheelhouse liner. Refer to *Front Wheelhouse Liner Replacement* in SI.
12. Install the windshield wiper motor. Refer to *Windshield Wiper Motor Replacement* in SI.
13. Remove fender covers and close hood.
14. Perform a water test to verify repair.

COURTESY TRANSPORTATION

The General Motors Courtesy Transportation program is intended to minimize customer inconvenience when a vehicle requires a repair that is covered by the New Vehicle Limited Warranties. The availability of courtesy transportation to customers whose vehicles are within the warranty coverage period and involved in a product program is very important in maintaining customer satisfaction. Dealers are to ensure that these customers understand that shuttle service or some other form of courtesy transportation is available and will be provided at no charge. Dealers should refer to the General Motors Service Policies and Procedures Manual for Courtesy Transportation guidelines.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below. All transactions should be submitted as a ZFAT transaction type, unless noted otherwise.

Labor Code	Description	Labor Time	Net Item
9101918	Apply Seam Sealer and Water Test	0.8	*

* The amount identified in “Net Item” should represent the actual sum total of the current GMCC&A dealer net price for the sealer needed to perform the required repairs, not to exceed \$10.00 USD (\$8.40 CAD), plus applicable Mark-Up or Landed Cost (for Export).

CUSTOMER NOTIFICATION

General Motors will notify customers of this program on their vehicle (see copy of customer letter included with this bulletin).

DEALER PROGRAM RESPONSIBILITY

All unsold new vehicles in dealers' possession and subject to this program must be held and inspected/repaired per the service procedure of this program bulletin before customers take possession of these vehicles.

Dealers are to service all vehicles subject to this program at no charge to customers, regardless of mileage, age of vehicle, or ownership, through November 30, 2017.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the involved vehicle listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Program follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this program enters your vehicle inventory, or is in your facility for service through November 30, 2017, you must take the steps necessary to be sure the program correction has been made before selling or releasing the vehicle.



December 2015

This notice applies to your vehicle, **VIN:** _____

Dear General Motors Customer:

We have learned that your 2016 model year Chevrolet Colorado or GMC Canyon may have been built with an improperly sealed vertical seam near the driver's side dash. This could allow water to leak onto the driver side floor, resulting in wet carpet or a mildew smell.

Your satisfaction with your Chevrolet Colorado or GMC Canyon is very important to us, so we are announcing a program to prevent this condition or, if it has occurred, to fix it.

What We Will Do: Your GM dealer will seal the vertical seam near the driver's side dash. This service will be performed for you at **no charge until November 30, 2017**. After that, any applicable warranty will apply.

What You Should Do: To limit any possible inconvenience, we recommend that you contact your dealer as soon as possible to schedule an appointment for this repair. By scheduling an appointment, your dealer can ensure that the necessary parts will be available on your scheduled appointment date.

If you have any questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	1-800-833-2438
GMC	1-800-462-8782	1-888-889-2438
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

We sincerely regret any inconvenience or concern that this situation may cause you. We want you to know that we will do our best, throughout your ownership experience, to ensure that your GM vehicle provides you many miles of enjoyable driving.

Terry M. Inch
Executive Director
Global Connected Customer Experience

GM CUSTOMER CARE AND AFTERSALES
DCS3848
URGENT - DISTRIBUTE IMMEDIATELY

Date: November 18, 2015

Subject: 15708 - Customer Satisfaction Program
Water Leak onto the Left Cabin Floor

Models: 2016 Chevrolet Colorado
2016 GMC Canyon

To: All Chevrolet, GMC Dealers

General Motors is releasing Customer Satisfaction Program 15708 today. The total number of U.S. vehicles involved is approximately 1,500. Please see the attached bulletin for details.

Customer Letter Mailing

The customer letter mailing will begin mid-December, 2015.

Global Connect (GWM)

The "Investigate Vehicle History" (IVH) screen will be updated November 19, 2015. A list of involved vehicles in dealer inventory is attached to this message.

Campaign Initiation Detail Report (CIDR)

The CIDR will be available in the near future.

GM CUSTOMER CARE AND AFTERSALES