

GROUP	MODEL
Chassis	2011-2013MY Sorento (XMa)
NUMBER	DATE
051	January 2015

TECHNICAL SERVICE BULLETIN

SUBJECT: COMBINED TSB / SERVICE ACTION: FRONT STRUT BEARING REPLACEMENT (SA 178)

This bulletin provides the procedure for replacing the front strut bearings on some 2011-2013MY Sorento (XMa) vehicles, produced from October 26, 2009 through January 21, 2013, which may exhibit a creaking noise emanating from the front of the vehicle when turning the wheel quickly, at slow speeds. To correct this condition, replace the front strut bearing by following the procedure outlined in this bulletin.

For vehicles not on the Affected Vehicles list, but with a customer concern as described above, perform the following procedure outlined in this bulletin and submit a warranty claim per "customer concern" (Standard TSB) claim information on page 10.



* NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service> Warranty Coverage> Warranty Coverage Inquiry> Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs> Not Completed Recall> Recall VIN> Select Report), which includes a list of affected vehicles.

This issue number is **SA178**.

File Under: Chassis

Circulate To:

General Manager

Service Manager

Parts Manager

☑ Service Advisor(s) ☑ Technician(s) ☑ Body Shop Manager ☑ Fleet Repair

COMBINED TSB / SERVICE ACTION: FRONT STRUT BEARING REPLACEMENT (SA 178)

Service Procedure:

- 1. Place the vehicle on the lift and remove the front wheels.
- Place the spring compressors side by side on a flat surface. Use a paint marker to add markings to the left side tool, as shown. NOTE: These markings will prevent over-tightening and possible damage to the tool when compressing the spring.



The spring compressors were autoshipped to each dealer for campaign **TSB** SC 091. If the spring compressors are no longer serviceable, ordering see the information on Page 9.



3. Remove the sway bar link nut (A).

* NOTICE

Retain all hardware for reuse.




4. Install coil spring compressors (B) on either side of the spring, as shown.

* NOTICE

Do not use the spring compressors if the plastic pads are damaged. Install replacements or order new spring compressors.






TSB: CHA 051 / SA 178 Sorento (XMa) January 2015

COMBINED TSB / SERVICE ACTION: FRONT STRUT BEARING REPLACEMENT (SA 178)

5. Tighten the coil spring compressors EVENLY from side to side. Use the white markings on the tool to avoid overcompressing the spring.



* TIP

Tighten the coil spring compressors until the alignment marks sit on either side of the guides. At this point, check to make sure that all tension has been removed from the spring.



6. Use a white paint marker to create an alignment mark on the flat surface of the strut shaft, as shown.


* TIP

During reassembly, make sure the white alignment mark on the strut shaft lines up with the white dot on the insulator pad.




COMBINED TSB / SERVICE ACTION: FRONT STRUT BEARING REPLACEMENT (SA 178)

7. Remove nut securing the shock assembly to the insulator pad, as shown.



8. Remove three nuts securing the insulator pad to the shock tower.



9. Locate the strut bearing remover tool.



COMBINED TSB / SERVICE ACTION: FRONT STRUT BEARING REPLACEMENT (SA 178)

10. Install the strut bearing remover onto the three studs protruding through the strut tower.



* TIP

The bolt heads should be tightened by hand until flush with the strut tower.



11. Lower the center bolt to compress the strut shaft.




COMBINED TSB / SERVICE ACTION: FRONT STRUT BEARING REPLACEMENT (SA 178)

12. To assist with reassembly, allow a gap of at least ½" ~ ½" between the bolt head and the shoulder of the strut bearing remover tool.



13. Locate the strut bearing remover cable and remove one side of the cable from the bracket.



14. Install the strut bearing remover cable around the top of the strut shaft, as shown.


* TIP

The strut bearing remover cable will prevent strut from protruding through the strut bearing/insulator pad.



COMBINED TSB / SERVICE ACTION: FRONT STRUT BEARING REPLACEMENT (SA 178)

15. Install the hook onto the caliper bolt and tighten the turn buckle to secure the strut shaft in place.



16. Back out the center bolt on the strut bearing remover in order to remove the bearing.



COMBINED TSB / SERVICE ACTION: FRONT STRUT BEARING REPLACEMENT (SA 178)

17. Pull coil spring to the side in order to gain access to the strut bearing. Replace the strut bearing with an improved part.



18. Lower the center bolt on the strut bearing remover tool and align it with the top of the strut shaft.

Once the strut is compressed by the strut bearing remover tool:

- 1. Remove the strut bearing cable
- 2. Guide strut through the insulator pad by backing out the center bolt on the strut remover tool.





- 19. Reinstall all removed components by reversing the order of removal.
- 20. Replace the upper strut bearing on the opposite side of the vehicle.

TSB: CHA 051 / SA 178 Sorento (XMa) January 2015

COMBINED TSB / SERVICE ACTION: FRONT STRUT BEARING REPLACEMENT (SA 178)

REQUIRED TOOL:

Part Name	Part Name Part Number			Comments	
Strut Bearing Remover SST	0K546 2B100FFF	1		Auto-shipped to Dealer	
Spring Compressor	09546 0W000	2	¢3	Auto-shipped to Dealer for TSB SC091. For additional Spring Compressors, contact Snap-On Business Solutions at 888-542-1011	

REQUIRED PARTS:

Part Name	Part No.	Qty.	Figure
Front Strut Bearing	54609 2P500FFF	2	

AFFECTED VEHICLE PRODUCTION RANGE:

Model	Production Date Range				
Sorento (XMa)	October 26, 2009 through January 21, 2013				

SERVICE ACTION CLAIM INFORMATION:

Claim Type	Causal P/N	Qty.	N Code	C Code	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	54612 2P000	0	N99	C99	(SA 178) Front Strut Bearing Replace (Front/Both)	140A06R0	0.7 M/H	54609 2P500FFF	2

COMBINED TSB / SERVICE ACTION: FRONT STRUT BEARING REPLACEMENT (SA 178)

STANDARD WARRANTY CLAIM INFORMATION:

Use this information only to file a warranty claim for vehicles for which:

- 1. A customer complains of the same concern, as described on Page 1.
- 2. The VIN does not appear on the Affected Vehicles list for Service Action 178.
- 3. The vehicle model year and production date range are as identified in this bulletin.

Claim Type	Causal P/N	Qty.	N Code	C Code	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
W	54612 2P000	0	Q85	ZZ7	(CHA 051) Front strut dust cover replacement (Front/Both)	54623F01	0.7 M/H	54609 2P500FFF	2

* NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA178 when accessing the WebDCS system.