	GROUP Chassis	MODEL 2014MY Sportage (SL)
	NUMBER 057	DATE April 2015
TECHNICAL SERVICE BULLETIN		
SUBJECT: TPMS SENSOR REPLACEMENT		

This bulletin provides the procedure to replace the TPMS sensors on some 2014MY Sportage (SL) vehicles, produced from September 1, 2013 through July 1, 2014, which may exhibit a TPMS light illuminated in the cluster, along with DTC C1212 - Vehicle Speed Sensor. To correct this concern, replace all four (4) TPMS sensors with the improved parts, by following the procedure outlined in this bulletin.

DTC C1212 – Vehicle Speed Sensor



File Under: <Chassis >

-
- Circulate To: General Manager Service Manager Parts Manager
 Service Advisor(s) Technician(s) Body Shop Manager Fleet Repair

Service Procedure:

1. Place the vehicle on the lift and remove all four (4) wheels.



2. Remove the valve cores from the valve stems and allow the tire to deflate.



3. Use a ruler and yellow chalk to make reference marks 2" to either side of the valve stem, as shown



CAUTION

To prevent damage to the TPMS sensor, avoid breaking the bead too close to the sensor. Any damage to the TPMS sensor during removal is NOT considered a warrantable repair.



SUBJECT:

TPMS SENSOR REPLACEMENT

4. Insert the machine's shoe into the bead to either side of the reference marks.



5. Use the machine's shoe to break the bead ONLY enough to expose the TPMS sensor. Then, remove the nut and pull the TPMS sensor from the wheel. **NOTE: Be careful NOT to drop the TPMS sensor inside the wheel/tire assembly.**



6. Install the new TPMS sensor onto the wheel and secure in place using the new nut.

**Torque TPMS nut to:
2.6 ~ 3.3 lb·ft (3.5 ~ 4.5 N·m)**



7. Inflate the tires to the proper pressure, as shown in the table.

Tire Size	Pressure (PSI)
P215/70R16	35 PSI
P225/60R17	
P235/55R18	34 PSI

8. Reinstall the wheels on the vehicle.

**Torque Lug Nuts to:
65.1 ~ 79.6 lb·ft (88.3 ~ 107.9 N·m)**



9. Register the new TPMS sensors by referring to “Suspension System → Tire Pressure Monitoring System → TPMS Sensor” chapter in the applicable Workshop Manual on KGIS.


SUBJECT:

TPMS SENSOR REPLACEMENT

AFFECTED VEHICLE PRODUCTION RANGE:

Model	Production Date Range
Sportage (SL)	From September 1, 2013 through July 1, 2014

PART INFORMATION:

Part Name	Part Number	Qty.	Figure
TPMS Assembly	52933 2S510U	4	

WARRANTY INFORMATION:

Claim Type	Causal P/N	Qty.	N Code	C Code	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
W	52933 2S510	0	I18	ZZ3	(CHA 057) TPMS Replace (4EA)	52933F00	0.9 M/H	52933 2S510U	4