

91 Rear Seat Entertainment software update for potential vehicle battery draw concern and improved functionality

91 16 41 2043660/2 April 27, 2016. Supersedes Technical Service Bulletin Group 91 number 16-34 dated March 23, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, Q7	2017 - 2019	All	Rear Seat Entertainment

Condition

REVISION	HISTORY	
Revision	Date	Purpose
2		Revised <i>Technical Background</i> (Completely revised) Revised <i>Service</i> (Completely revised)
1	3/23/2016	Initial publication

One of the following conditions is present in a vehicle equipped with Rear Seat Entertainment (RSE) tablets:

- The customer has various complaints about the RSE system and would like to update the software of the RSE tablets.
- The vehicle cannot be started after it has been off for several days, and there are no indications in the battery history log of battery drain originating from a control unit on the CAN bus.

Technical Background

Periodically, software updates are made available for the RSE systems to fix various concerns and to improve the user experience. The March 2016 update (010008) implemented a fix that can prevent one of the RSE units from staying awake while the ignition is off, which can potentially draw the vehicle battery down. The latest update, 010101 (available as of April 2016), has the following improvements:

- Improved media playback compatibility.
- Improved stability and compatibility with Audi RSE remote app.
- The RSE III music player will now always prefer to connect to the Audi MMI via Bluetooth (Not Google Music).
- Improved music player priority handling (for users with multiple music playback apps).
- When throwing movies from one RSE III to another, the movie will always continue at the same position.
- · General updates: Improved system stability and security.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Production Solution

New RSE units available from Audi Genuine Accessories will already be updated with the new software.

Service

The Android system software will need to be updated via an internet connection. The update can be performed with the tablets inside or outside of the vehicle. It is recommended that the update is performed outside of the vehicle with the tablets plugged into a wall charger, using a micro USB cable and charger (a standard micro USB smartphone cell phone charger can be used).

1. Before proceeding, ensure that the following conditions are true:

- The tablets have a battery charge level of 100% and can remain connected to a power source while the update is completed. This is critical. Once the installation starts, the tablet may NOT charge during this process. If the tablet has less than 100% charge then it may die during the installation process. It is recommended that the tablets reach 100% charge level before the installation process is started.
- IF UPDATING THE TABLETS INSIDE OF THE VEHICLE: The vehicle is attached to a battery charger, or the vehicle can be powered on for at least one hour (the engine should be left running to prevent battery drain). Depending on the Wi-Fi download speeds, the car may need to be on for a much longer period of time. Updating the tablets while installed inside the car is not recommended for slow Wi-Fi connections.
- IF UPDATING THE TABLETS OUTSIDE OF THE VEHICLE: Plug a good working micro USB cable and charger into the side of both the tablets (Figure 1). The charger should support at least a 1A supply (Figure 2) to the tablet. (Do not plug the USB cable into a PC or laptop; the cable must be plugged into a wall outlet). Most modern Android cell phones have chargers that support this higher current supply, whereas a flip phone chargers do not. Optionally, an Apple charger connected with a micro USB cable can be used. All Apple iPhone wall chargers have a minimum of 1A current supply.



Figure 1. Micro USB charge port.

© 2016 Audi of America, Inc.

Page 2 of 7

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.





Figure 2. USB Smartphone charger with 1A current supply capability.

- An active Wi-Fi hotspot with high speed internet must be available. An active Wi-Fi hotspot is required because the update is performed over the internet. The system cannot be updated via SD card or any other type of media.
- Note that the update may take longer if the Wi-Fi has poor download speeds. Typically, the "Guest" Wi-Fi access in a dealer showroom is not fast enough to allow this update. If a slow Wi-Fi is being used, performing this update is NOT recommended.

Note that if the vehicle's hotspot is being used, and the customer's subscription is not on the six-month Audi trial, the subscription will have a limited amount of data. For subscriptions actively on the six-month Audi trial, LTE data is unlimited from the vehicle Wi-Fi hotspot. For reference, future updates can consume as much as 0.8GB of data, but this initial update can be as large as 600MB or as little as 15MB, depending on the starting software level.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



 Check the software version of each RSE tablet from the main menu by selecting *Settings>>Device Settings>>About Tablet>>Custom build version* (Figure 3 - Figure 6).

The version of the custom build is displayed in following format, where the "010006" denotes the system software level:

RSEIII.010006.XXXXXXX_XXXX

If the software level is less than 010101:

A software update is available. Proceed to the next step.

If the software level is 010101:

 The software is already up-to-date as of April 2016. A newer update may be made available at a later date.



Figure 3. Settings option in main menu.

< Settin	ngs
Language	
Background Image 6	Amblent Light
Screen Output	
Device Name	
Device Settings	

Figure 4. Device settings.

O, Settin					
	Battery				
	Apper				
	FERDOMAL				
	Location				
	B Security				
	Language & irout				
	O Backup & weet				
	ACCOUNTS .				
	Coople				
	+ Addaecourt				
	(TTTD4)				
	Date & time				
	Accessibility				
	Planting				
	O About tablet				
		+= ·	0	-C37	

Figure 5. About tablet.

C 2016 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Audi Entertainment mobile System Update
Status
Status of the bettery, network, and other information
Legal information
Model number
HSEH
Android version
442
Kernel version
3.4.67 sebastian@o6207231.#1
Fo Sep 4 18:004 C07 2015
Build number
ALPSIXKI MPIGVI.6
Custom build version
RSEII.010001.20150831_M25A

Figure 6. Custom build version.



Figure 7. Check for System Update.

< Update available		
Change Log	Retraise Date: Feb 22, 2016	
	Version: 3.0.8	
This update resolves potential issues while charging the AIM aning the car battery.	Sze 71.1640	
		Deventional

Figure 8. Update available.

 To perform the software update, go to the top of the screen and select: Audi Entertainment Mobile System Update>>Check Now (Figure 7).

4. If an update is available, an information screen will appear with the new version number, change log, and release date (Figure 8). Select the *Download* option to begin the download of the update. Depending on the size of the update and the speed of the Wi-Fi connection, it can take a few minutes to several hours to download the update. In most cases it only takes a few minutes.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.




 After the update file has been downloaded to the RSE tablet, the option to start the install will be provided. Ensure that the tablet battery charge level is 100% before starting the install.

Select *Install now* (Figure 9). Depending on the size of the update, it can take a few minutes to up to an hour to complete the update.

Once the update is installed, the Android tablet will restart and complete the update (Figure 10). It is critical the tablet does not lose power at this point. If the battery of the tablet drains completely, it is possible the tablet will become useless and need a factory reset. If this happens, contact TAC.





/ideos	You are no	n complete w using the l Audi Enterta	atest inment	James
VIGEOS		ок		1011103
-		•		පුර
	Apos		HOHI-IN	

Figure 10. Installation complete.

Note: If the installation hangs at "Andy the Android" and does not progress (Figure 11), turn off the tablet by holding the power button until the screen goes black. Then, allow the tablet to charge for at least four hours. After charging, turn the tablet on and the installation should start again. Keep the tablet connected to the charger while the installation completes. Repeat this process if the installation fails a second time.

C 2016 Audi of America, Inc.



Figure 11. Generic image of Android firmware installation screen.

Page 6 of 7

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Warranty

Claim Type:	12i				
Service Number:	9104				
Damage Code:	0039				
Labor Operations:	Update software of two RSE tablets 9104 9999 25 TU				
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	No allowance	0 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2043660/2				

All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2043660) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.