

TECHNICAL BULLETIN  
K280 UPS4315-1bNAS1  
21 APR 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

**SECTION: 204-00**

Update Prior to Sale: Carry Out Rear Toe Adjustment

**AFFECTED VEHICLE RANGE:**

**F-TYPE (X152)**

**Model Year:** 2016

**VIN:** GMK20367-GMK24640

**MARKETS:**

NAS

**CONDITION SUMMARY:**

**Situation:** An issue has been identified on a limited number of 2016 model year F-TYPE (X152) vehicles which require a rear toe alignment check.

**Action:** Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

**PARTS:**

No parts required

**SPECIAL TOOLS:**

Refer to Workshop Manual/Service Instruction for any required tools

**WARRANTY:**



**NOTE: check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.**

At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **20 October 2015** closure date must be submitted quoting Program Code '**K280**' together with the relevant Option Code from the table. The SRO and part information listed have been included for information only. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

Repair procedures are under constant review, and therefore times/prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIX to obtain the latest repair time.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE
K280	B	Carry out rear toe adjustment	57.65.15	0.70	-	-
K280	C	Carry out rear toe adjustment Drive in/drive out	57.65.15 10.10.10	0.70 0.20	- -	- -

Normal Warranty policies and procedures apply

**SERVICE INSTRUCTION:**

1. Carry out rear toe adjustment (see TOPIx Workshop Manual, section 204-00).