

# TECHNICAL BULLETIN

## K309NAS1

### 02 NOV 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

### **SECTION: 303-00**

#### Service Action: Oxygen (O2) Sensors

#### **AFFECTED VEHICLE RANGE:**

##### **F-TYPE (X152)**

**Model Year:** 2014-2016  
**VIN:** K00001-K29970  
**Manufacturing Plant:** Castle Bromwich

**Engine:** V6 S/C 3.0L Petrol  
 V8 S/C 5.0L Petrol

##### **XF (X250)**

**Model Year:** 2013-2015  
**VIN:** S50937-U88782  
**Manufacturing Plant:** Castle Bromwich

**Engine:** V6 S/C 3.0L Petrol  
 V8 5.0L Petrol  
 V8 S/C 5.0L Petrol

##### **XJ Range (X351)**

**Model Year:** 2013-2015  
**VIN:** V34129-V90847  
**Manufacturing Plant:** Castle Bromwich

**Engine:** V6 S/C 3.0L Petrol  
 V8 5.0L Petrol  
 V8 S/C 5.0L Petrol

#### **MARKETS:**

NAS

#### **CONDITION SUMMARY:**

**Situation:** To address concerns with the correct operation of the Oxygen (O2) Sensors, updated Engine Control Module (ECM) software is required on the models, engine variants, and Vehicle Identification Number (VIN) ranges as listed in the Affected Vehicle Range.

**Action:** Retailers are required to HOLD only affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

#### **PARTS:**

No parts required.

#### **SPECIAL TOOLS:**



**NOTE:** this 'Active Bulletin' will display a functional programming shortcut if accessed within a diagnostic session using SDD.