Reference	SSM72458
Models	XF / X260
Title	X260 - P208B-00 Reductant Pump `A` Control Performance/Stuck Off (Low mileage vehicles only)
Category	Engine
Last modified	08-Oct-2015 00:00:00
Symptom	403000 Exhaust System Concerns
_	

Content

<u>Issue:</u> Customers may report engine management light (MIL) illuminated during the first 1000miles of usage from delivery, with the possibility of a 'No engine restarts in xxx miles, diesel exhaust fluid dosing malfunction" warning message displayed within the instrument cluster message center and DTC's logged P208B-00/P2BAE-00/P2BAF-00.

Cause: Under investigation

<u>Action:</u> Please complete the following routine, this will prime, purge and pressure test the DEF/SCR system:

- 1. Start SDD session and enter the service functions (DVD143 Patch 3 onwards)
- 2. Under the powertrain section run the 'Diesel exhaust fluid prime and pressure test routine' and the 'Reset selective catalyst reduction quality monitor'
- 3. Once completed successfully, clear the fault codes

Please note: Upon fault clear, the warning changes to "No engine restarts in xxx miles, diesel exhaust fluid dosing malfunction" also make sure the engine MIL is off (when engine is running).

- 4. Complete the following drive cycle making sure the DEF system monitor conditions are met:
 - Drive the vehicle at 'urban' speeds (<50mph) and light engine load
 - Make sure the exhaust temperature remains under 300degC or 572degF (use data logger if required)
 - The 'inducement' warning clears automatically once the monitoring has executed. This terminates the driving cycle.

Please Note - If the engine MIL shows during the driving cycle, the malfunction has reoccurred which will require further diagnosis on the SCR/DEF system 5. Clear Faults/PCodes after the driving cycle, this clears up the DTC's P2BAE/P2BAF $\,$