



ABOVE & BEYOND

## SERVICE ACTION Q485: MALFUNCTION INDICATOR LAMP (MIL) P2183-00 STORED

## SERVICE BULLETIN

29-MAY-15

NO.: SGI15-14

SECTION: GENERAL  
INFORMATION

MARKET: CAN / USA

### DESCRIPTION

An issue has been identified on a limited number of 2015 model year LR4 (L319) vehicles where the engine Malfunction Indicator Lamp (MIL) may be illuminated and Diagnostic Trouble Code (DTC) P2183-00 may be stored in the Engine Control Module.

### AFFECTED VEHICLES

The VIN range of affected vehicles is FA726091-FA765550.

### ACTION TO BE TAKEN

Check DDW to ensure that the vehicle is affected by this program (Q485) prior to undertaking any rework action.

Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the rework action.

Sold vehicles will be subject to the standard Recall notification and Recall bulletin process detailing the action required for vehicles in the hands of owners.

Refer to Technical Bulletin Q485NAS, *Service Action: Malfunction Indicator Lamp (MIL) P2183-00 Stored*, for detailed repair instructions.

### PARTS

No parts required.

### TOOLS

Refer to the Technical Bulletin noted above for any required tools.

### WARRANTY

**NOTE: check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.**

At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code 'Q485' together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **31 May 2017** expiry date must be submitted for payment within 30 calendar days of completion of the repair.

<b>PROGRAM CODE</b>	<b>OPTION CODE</b>	<b>DESCRIPTION</b>	<b>SRO</b>	<b>TIME (HOURS)</b>	<b>PART No. / SUNDRY CODE</b>	<b>QTY. / VALUE</b>
<b>Q485</b>	<b>B</b>	Configure the ECM	12.90.13	0.20	-	-
<b>Q485</b>	<b>C</b>	Configure the ECM	12.90.13	0.20	-	-
		Drive in/drive out	02.02.02	0.20	-	-

*Normal Warranty policies and procedures apply*