



ABOVE & BEYOND

SERVICE ACTION Q470: BLINDSPOT MONITORING CONTROL MODULE

SERVICE BULLETIN

05-JUN-15

NO.: SGI15-16

SECTION: GENERAL INFORMATION

MARKET: CAN / USA

DESCRIPTION

A potential issue has been identified on 2015 model year LR4 (L319), Range Rover Evoque (L538), Range Rover Sport (L494), and Range Rover (L405) vehicles where the Blindspot Monitoring Control Module (BMCM) may experience water ingress.

AFFECTED VEHICLES

The VIN ranges of affected vehicles are:

- LR4 (L319) FA756360-FA758704
- Range Rover Evoque (L538) FH032201-FH037806
- Range Rover Sport (L494) FA516840-FA518618; FA612221-FA614389
- Range Rover (L405) FA212907-FA215734

ACTION TO BE TAKEN

Check DDW to ensure that the vehicle is affected by this program (Q470) prior to undertaking any rework action.

Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the rework action.

Refer to Technical Bulletin Q470NAS, *Service Action: Blindspot Monitoring Control Module*, for detailed repair instructions.

PARTS

NOTE: when ordering parts, only order the expected percentage demand of parts identified

DESCRIPTION	PART No. / SUNDRY CODE	QTY. / VALUE	EXPECTED % OF VEHICLES REQUIRING PARTS
Blindspot monitoring control module - LR4 (L319), Range Rover Evoque (L538)	LR052073	2	100
Blindspot monitoring control module - Range Rover Sport (L494)	LR054577	2	100
Blindspot monitoring control module - Right-hand - Range Rover (L405)	LR071744	1	100
Blindspot monitoring control module - Left-hand - Range Rover (L405)	LR071747	1	100

TOOLS

Refer to the Technical Bulletin noted above for any required tools.

WARRANTY

NOTE: check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code 'Q470' together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the 30 June 2017 expiry date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART No. / SUNDRY CODE	QTY. / VALUE
Q470	B	LR4 (L319), Range Rover Evoque (L538) Blindspot monitoring control modules – renew	86.54.93	1.3 - LR4 (L319) 1.2 - Range Rover Evoque (L538)	LR052073	2
		Configure the side object detection modules	86.90.86	0.3		
Q470	C	LR4 (L319), Range Rover Evoque (L538) Blindspot monitoring control modules – renew	86.54.93	1.3 - LR4 (L319) 1.2 - Range Rover Evoque (L538)	LR052073	2
		Configure the side object detection modules	86.90.86	0.3		
		Drive in/drive out	02.02.02	0.2		
Q470	F	Range Rover Sport (L494) Blindspot monitoring control modules – renew	86.54.93	1.3	LR054577	2
		Configure the side object detection modules	86.90.86	0.3		
Q470	G	Range Rover Sport (L494) Blindspot monitoring control modules – renew	86.54.93	1.3	LR054577	2
		Configure the side object detection modules	86.90.86	0.3		
		Drive in/drive out	02.02.02	0.2		

Q470	K	Range Rover (L405)				
		Blindspot monitoring control modules – renew	86.54.93	0.9	LR071744 LR071747	1 1
		Configure the side object detection modules	86.90.86	0.3		
Q470	L	Range Rover (L405)				
		Blindspot monitoring control modules – renew	86.54.93	0.9	LR071744 LR071747	1 1
		Configure the side object detection modules	86.90.86	0.3		
		Drive in/drive out	02.02.02	0.2		

Normal Warranty policies and procedures apply