TECHNICAL BULLETIN LTB00676NAS2 05 OCT 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

This reissue replaces all previous versions. Please destroy all previous versions.

Changes are highlighted in gray

SECTION: 501-09

Powerfold Door Mirrors - Judders During Powerfold Operation and/or is Loose/Vibrates

AFFECTED VEHICLE RANGE:

LR4 (LA)

Model Year: 2010 Onwards

510742 Onwards With: Power Folding Mirrors

Manufacturing Solihull

Plant:

LR2 (LF)

Model Year: 2008-2015

000212-439912 With: Power Folding Mirrors

Manufacturing Halewood

Plant:

LR3 (LA)

Model Year: 2005-2009

000256-513325 With: Power Folding Mirrors

Manufacturing Solihull

Plant:

Range Rover Sport (LS)

Model Year: 2006-2013

900129-814822 With: Power Folding Mirrors

Manufacturing Solihull

Plant:

MARKETS:

NAS

CONDITION SUMMARY:

Situation: The door mirror may 'judder' during powerfold (manual or automatic) operation and/or may be loose or vibrates.

Cause: This may be caused by a tolerance stack-up between the door mirror and the door and/or the retaining screws may be loose/under torqued.

Action: Should a customer express this concern, follow the appropriate Service Instruction [A or B] outlined below.

PARTS:

WC105002 Washer Quantity: 4 (2 per

side)

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

NOTE: DDW requires the use of causal part numbers. Labor only claims must show the

causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Door mirror - Powerfold - Diagnosis and rectification	76.11.89.67	0.2	41	LR041878
Door mirror - Powerfold - Diagnosis and rectification - Vehicle set - LR3 (L319), LR4 (L319), Range Rover Sport (L320)	76.11.89.95	0.5	41	LR041878
Door mirror - Powerfold - Diagnosis and rectification - Vehicle set - LR2 (L359)	76.11.89.95	0.4	41	LR041878

NOTE: Normal Warranty procedures apply.

SERVICE INSTUCTION 'A' - 'Judder' Concern Only


LR3 (L319), LR4 (L319), Range Rover Sport (L320) vehicles only

NOTE: Service Instruction 'A' to be performed for a 'judder' during powerfold operation concern only.

1 CAUTION: make sure no damage is caused to the powerfold door mirror.


CAUTION: do not apply any form of external lubrication, as this will have no effect to the internals of the mechanism and may cause damage.

Manually move the powerfold door mirror forwards and backwards 20 times, then return the powerfold door mirror to the central position.



2 NOTE: do not disconnect the powerfold door mirror - trim electrical connector.


Release the powerfold door mirror - interior trim.



3 CAUTION: take care not to damage the paint on the vehicle.

NOTE: do not disconnect the powerfold door mirror electrical connector.

Release the powerfold door mirror.




4Install the washers to the powerfold door mirror lower retaining bolts only.




5Install the powerfold door mirror.

• Torque: 6 Nm



6Check the operation of the powerfold door mirror.

7Install the powerfold door mirror - interior trim.




SERVICE INSTRUCTION 'B' - Loose/Vibration Concern Only

Vehicles with removable powerfold mirror covers.

NOTE: Service Instruction 'B' to be performed for a loose/vibration concern only.

NOTE: right-hand side shown; left-hand side similar

Remove the door mirror cover.



2 NOTE: if the screws are loose the mirror head will be loose or vibrate.

Tighten the powerfold door mirror head screws.

• Torque: 2 Nm



- **3**Check the operation of the powerfold door mirror.
- **4**Install the powerfold door mirror cover.

