

TECHNICAL BULLETIN
LTB00858NAS1
09 NOV 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 412-00

High-Pitched 'Whistle' Noise From The Climate Control System

AFFECTED VEHICLE RANGE:

LR4 (LA)

Model Year: 2014 Onwards
VIN: 699716 Onwards
Manufacturing Plant: Solihull

MARKETS:

NAS

CONDITION SUMMARY:

Situation: A high-pitched 'whistle' noise may be evident from the instrument panel area when the climate control system is in use and engine speed is between 2,000 and 3,000 rpm.

Cause: This may be caused by a resonance within climate control system Air Conditioning (A/C) pipes.

Action: Should a customer express this concern, follow the Service Instruction below.

PARTS:

No Parts Required

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Air conditioning system - Depressurize - Evacuate - Capture and recharge	82.30.02	1.10	42	LR013849

 **NOTE: Normal Warranty procedures apply.**

SERVICE INSTRUCTION:

1  **CAUTION: 50ml of PAG OIL -SP-A2 must be added to the Air Conditioning (A/C) system.**

Recover, evacuate, and charge the Air Conditioning (A/C) system (see TOPIx Workshop Manual section 412-00: Climate Control System > General Information > Air Conditioning (A/C) System Recovery, Evacuation and Charging).