Reference	SSM72565
Models	Discovery Sport / L550
	Range Rover Evoque / L538
Title	L550 + L538, HVAC incorrect function - Airflow not as expected, loss of climatic seat control
Category	Electrical
Last modified	19-Dec-2015 00:00:00
Symptom	208000 Climate Control
Content	Jeane.

Content

Issue:

Customers may report loss of climate control in HVAC system and/or seat heating, which is due to HVAC software communication issues on the LIN Bus.

The communication ceases upon shutdown and does not recover upon wake up.

Symptoms include:

- DTC's.
- HVAC blower becomes inoperative because there is no Stepper Control.
- No LIN communication to the seats and therefore, no climate seat control.

Cause:

HVAC software.

Action:

The following method will load a software file to SDD using the Manual Patch Update process.

This Manual Patch will stay on the SDD machine.

- 1. Login to SDD.
- Select 'Continue' on the SDD Warning screen.
- 3. Select 'Settings' tab.
- Select 'System Utilities'.
- 5. Select 'Manual Patch Update'.
- 6. A pop-up will be displayed for Manual patch selection dialog box.
- 7. Enter 'MP JLR R0002' in the Manual patch selection dialog box.
- 8. Select 'OK'.
- 9. The 'Software Management Wizard' will then download the fix file.
- 10. The Manual patch update information pop up will ask 'Do you want to install the update now?' Select 'OK'.
- 11. Select 'OK' when the message 'Please shut down SDD before continuing' is displayed. DO NOT SHUT DOWN THE PC.
- 12. 'Please wait' message is displayed.

- 13. Select 'OK' when the 'Package has been installed' message is displayed.
- 14. Select 'OK' in the Manual patch update information pop up.
- 15. Close the Internet Explorer Window where the SDD program runs.
- 16. Start a new SDD session.
- 17. Program the Heating Ventilation Air Conditioning control module (HVAC).
- 18. Close the SDD session.

If this Manual patch fails to correct the concern then a Technical Assistance should be escalated.

Note: If this manual patch is not being installed on all SDD machines you may wish to consider labelling the machine.