

Models: Multistrada 1200 Model Year 15-17 (all model and country versions)

Multistrada 1200 Model Year 10-14 (all model and country versions)

Multistrada 1200 Enduro Model Year 16-17 (all country versions) Diavel Model Year 15-17 (all model and country versions)

XDiavel Model Year 15-17 (all model and country versions)

XDiavel Model Year 16-17 (all model and country versions)

# Electronic Service Bulletin SRV-ESB-16-003

Date: Monday, May 31, 2016

To: Dealer Principal, General Manager, Service Manager, and Service Technician From: Richard Kenton, Technical Director; Jonathan LaForte, Technical Manager

#### Dear Ducati Dealer,

As you may already know, the quality tests that we constantly perform on our products, combined with the analysis of your feedback on motorcycles in the field, have helped develop a new generation fuel level sensor.

As a result of the higher reliability of the new component, we have developed the following procedure to avoid unnecessary replacement of the fuel level sensor in case the end customer would report an incorrect fuel level indication being displayed on the instrument panel.

After the verification, if the component needs to be replaced, it will be necessary to fill a YouTech Assistance Request and to attach to it the technical datasheet (SRV-ESB-16-003 Attachment.pdf), in order to receive authorization for the repair.



#### NOTE

Requests for fuel level sensor replacements that lack proper YouTech reporting and supporting documentation will be sent back for correction. To assure the best customer service, please ensure that all required data are supplied in the initial request.

## Verification procedure

This objective method is based on the measurement of the resistance between the two PINs of the fuel level sensor connector (component side wiring). This measurement corresponds to a unique position of the inner float of the sensor.

The method involves 4 different STEPS that must be carried out in the proper, indicated sequence. Thoroughly follow the instructions of each step.

- This test can be carried out regardless of the fuel quantity in the tank;
- Position the motorcycle on the rear paddock stand or on the central stand, if available.
- By means of a multimeter set to ohm, measure the <u>resistance between the two PINs of the fuel level sensor connector</u> (component side wiring). The values detected must be compared with the values indicated in the tables of each verification step.



Models: Multistrada 1200 Model Year 15-17 (all model and country versions)
Multistrada 1200 Model Year 10-14 (all model and country versions)
Multistrada 1200 Enduro Model Year 16-17 (all country versions)

Diavel Model Year 15-17 (all model and country versions) XDiavel Model Year 16-17 (all model and country versions)

# Electronic Service Bulletin SRV-ESB-16-003



Refer to the measurement unit shown on the multimeter display:

| 1 Ω  | 1 ohm         |
|------|---------------|
| 1 kΩ | 1,000 ohm     |
| 1 ΜΩ | 1,000,000 ohm |

### STEP 1

Check the part number of the fuel level sensor indicated on the label on the sensor wiring pigtail, and record it in the technical data sheet for the request of fuel level sensor replacement under warranty – SRV-ESB-16-003 ING Annex.pdf.

The part numbers of the current fuel level sensors managed in the spare part warehouse are:

| Model                           | Fuel level sensor part number |
|---------------------------------|-------------------------------|
| Multistrada 1200 MY10-17        | 59210211D                     |
| Multistrada 1200 Enduro MY16-17 | 59210221C                     |
| Diavel MY15-17                  | 59210221C                     |
| XDiavel MY16-17                 | 59210242B                     |



Models: Multistrada 1200 Model Year 15-17 (all model and country versions)
Multistrada 1200 Model Year 10-14 (all model and country versions)
Multistrada 1200 Enduro Model Year 16-17 (all country versions)

Diavel Model Year 15-17 (all model and country versions) XDiavel Model Year 16-17 (all model and country versions)

# Electronic Service Bulletin SRV-ESB-16-003

## STEP 2

Measure the resistance value between the PINs of the fuel level sensor connector.

Write the "Resistance at workshop admittance" value in the appropriate field of the technical data sheet.

## Does this value fall within the range indicated in the table?

| Model                           | Comparison values<br>"Resistance at workshop admittance" STEP 2 |                            |
|---------------------------------|---|----------------------------|
|                                 | MINIMUM value [ $\Omega$ ]                                      | MAXIMUM value [ $\Omega$ ] |
| Multistrada 1200 MY10-17        | 240   | 55 000                     |
| Multistrada 1200 Enduro MY16-17 | 140   | 55 000                     |
| Diavel MY15-17                  | 140   | 55 000                     |
| XDiavel MY16-17                 | 500   | 55 000                     |

| V                   | YES, the value falls within range indicated in the table | *   | NO, the value does not fall within range indicated in the table |
|---------------------|--|---|---|
|                     |  | Repeat the measurement checking the correct contact of connector PINs and multimeter settings.  |   |
| Proceed with STEP 3 | that there   | easured value is still outside the range, it means e is a problem either in the wiring of the fuel level r or in the connector or inside the sensor itself. |   |
|                     |  | I the fuel level sensor require replacing, fill in a ech request enclosing pictures of the values detected with the multimeter.                             |   |



Models: Multistrada 1200 Model Year 15-17 (all model and country versions)

Multistrada 1200 Model Year 10-14 (all model and country versions) Multistrada 1200 Enduro Model Year 16-17 (all country versions)

Diavel Model Year 15-17 (all model and country versions) XDiavel Model Year 16-17 (all model and country versions)

# Electronic Service Bulletin SRV-ESB-16-003

#### STEP 3

## Does the value of "Resistance at workshop admittance" fall within the range indicated in the table?

| Model                           | Comparison values<br>"Resistance at workshop admittance" STEP 3 |                            |
|---------------------------------|---|----------------------------|
|                                 | MINIMUM value [ $\Omega$ ]                                      | MAXIMUM value [ $\Omega$ ] |
| Multistrada 1200 MY10-17        | 240   | 440                        |
| Multistrada 1200 Enduro MY16-17 | 47,000  | 55.000                     |
| Diavel MY15-17                  | 140   | 255                        |
| XDiavel MY16-17                 | 47,000  | 55,000                     |



YES, the value falls within range indicated in the table



NO, the value does not fall within the range indicated in the table

### Add 8 liters of fuel in the tank.

Measure again the resistance between the PINs of the fuel level sensor connector (component side wiring).

Write the "Resistance with 8 liters" value in the appropriate field of the technical data sheet.

Is the "Resistance with 8 liters" value different from the the value of "Resistance at workshop admittance"?

Proceed with STEP 4



YES. the values are the different

NO. the values are the same

The fuel level sensor works correctly.

fuel level sensor. Fill in a YouTech request enclosing pictures of the values detected with the

It is necessary to replace the

It is NOT necessary to replace the component.

Ducati North America www.ducatiusa.com

10443 Bandley Drive Cupertino, CA 95014 Tel. +1 408 253 0499 Fax +1 408 253 4099

multimeter.



Models: Multistrada 1200 Model Year 15-17 (all model and country versions) Multistrada 1200 Model Year 10-14 (all model and country versions)

Multistrada 1200 Induer Fear 10-14 (all Hoder and Country Versions)

Diavel Model Year 15-17 (all model and country versions) XDiavel Model Year 16-17 (all model and country versions)

## Electronic Service Bulletin SRV-ESB-16-003

### STEP 4

## Does the "Resistance at workshop admittance" value comply with the values indicated in the table?

| Model                           | Comparison values "Resistance at workshop admittance" STEP 4 [ $\Omega$ ] |
|---------------------------------|---|
| Multistrada 1200 MY10-17        | > 440   |
| Multistrada 1200 Enduro MY16-17 | < 47 000  |
| Diavel MY15-17                  | > 255   |
| XDiavel MY16-17                 | < 47 000  |



YES, the value detected complies with the reference value listed in the table



NO, the value detected does NOT comply with the reference value listed in the table

Remove all fuel present in the tank.

Do NOT remove the tank of the motorcycle during this operation to avoid releasing the inner float of the sensor.

Measure the resistance again. In the appropriate field of the technical data sheet, write the "Resistance after emptying" value.

Does this value fall within the range indicated in the table?

| Model                           | Resistance after emptying [ $\Omega$ ] |
|---------------------------------|--|
| Multistrada 1200 MY10-17        | 400 ± 40                               |
| Multistrada 1200 Enduro MY16-17 | 51 000 ± 4 000                         |
| Diavel MY15-17                  | 240 ± 15                               |
| XDiavel MY16-17                 | 51 000 ± 4 000                         |

Go back to STEP 2



YES, the value falls within the range indicated in the table



NO, the value does NOT fall within the range indicated in the table

The fuel level sensor works correctly.

It is NOT necessary to replace the component.

It is necessary to replace the fuel level sensor. Fill in a YouTech request enclosing pictures of the values detected with the multimeter.

10443 Bandley Drive



Models: Multistrada 1200 Model Year 15-17 (all model and country versions) Multistrada 1200 Model Year 10-14 (all model and country versions)

Multistrada 1200 Enduro Model Year 16-17 (all country versions)

Diavel Model Year 15-17 (all model and country versions) XDiavel Model Year 16-17 (all model and country versions)

## Electronic Service Bulletin SRV-ESB-16-003

At the end of the diagnosis procedure, carry out the "Fuel level reset" procedure from the "Settings" section of the self-diagnosis of the BBS, if possible. This adjustment is available today only for the following models:

- XDiavel Model Year 2016 and 2017;
- Multistrada 1200 Enduro Model Year 2016 and 2017.

Find below a summary table of the resistance values of the fuel level sensor both with empty and full tank:

| Model                           | Empty tank resistance [Ω] (it corresponds to the all down float position) | Full tank resistance [Ω] (it corresponds to the all up float position) |
|---------------------------------|---|--|
| Multistrada 1200 MY10-17        | 400 ± 40  | 51 000 ± 4000  |
| Multistrada 1200 Enduro MY16-17 | 51 000 ± 4 000  | 240 ± 15   |
| Diavel MY15-17                  | 240 ± 15  | 51 000 ± 4 000   |
| XDiavel MY16-17                 | 51 000 ± 4 000  | 800 ± 50   |

#### NOTE



At the lower ranges of the Multistrada MY10-17 and Diavel MY15-17 fuel level senor the resistance is not linear, in regards to float position. As such, it is possible for the measured resistance to be outside the values listed in the above table. It is critical, therefore, to exactly follow the instructions provided, to avoid erroneous results.

Beginning 7/19/2016 for any fuel level sensor warranty request it will be necessary to deliver to your Service Area Manger the technical data sheet for the request of fuel level sensor replacement under warranty (SRV-ESB-16-003 Attachment.pdf). This will allow us to better identify and analyze the real faults.

This sheet must be filled in every part and attached (in either pdf format, or an image of picture of the form filled in by hand) to the warranty pre-authorization YouTech request. Your Service Area Manager will assess the request according to the information specified in it and may request return of the fuel level sensor to the factory for quality analysis. Any fuel level sensor replacement performed without a properly filled in YouTech request with attached technical data sheet for the request of fuel level sensor replacement may be subject to rejection or chargeback of the NDCS claim.



Models: Multistrada 1200 Model Year 15-17 (all model and country versions)


Multistrada 1200 Model Year 10-14 (all model and country versions)

Multistrada 1200 Enduro Model Year 16-17 (all country versions)

Diavel Model Year 15-17 (all model and country versions) XDiavel Model Year 16-17 (all model and country versions)

# Electronic Service Bulletin SRV-ESB-16-003

Technical data sheet for the request of fuel level sensor replacement under warranty (SRV-ESB-16-003 Attachment.pdf)



### Warranty reimbursement rules

Reimbursement for authorized fuel level sensor replacements will be according to the following rules:

- Motorcycle is covered by warranty: reimbursement will be through the normal warranty channels -NORM type of NDCS claim;
- Motorcycle is not covered by warranty: it is necessary to check that the maintenance history of the
  motorcycle is complete and, if this is the case, ask for a reimbursement of the component only (labor
  excluded) GWIL type of NDCS claim;



Models: Multistrada 1200 Model Year 15-17 (all model and country versions)
Multistrada 1200 Model Year 10-14 (all model and country versions)
Multistrada 1200 Enduro Model Year 16-17 (all country versions)

Diavel Model Year 15-17 (all model and country versions) XDiavel Model Year 16-17 (all model and country versions)

# Electronic Service Bulletin SRV-ESB-16-003

For the operations performed to fill in the *Technical data sheet for the request of fuel level sensor replacement* you will be reimbursed for a labor time of 12 minutes (2UL); you can request a warranty reimbursement by providing the information below:

| Operation Code | 3 - 999 - 059 |
|----------------|---------------|
| -              |               |

We would like to remind you that the components replaced under warranty must NOT be scrapped and must be kept for at least 90 days, as it could be necessary to return the replaced sensors to DMH for further analysis. Should this be the case you will be contacted by your Service Area Manager.

Best regards,

Ducati North America Service Department