

Content

With the upcoming launch of the new CX-9, Mazda Technical Services Division is confident we can work together to deliver a premium vehicle to our customers. When performing a PDI, we ask that you closely inspect the following items to ensure they are correct.

Item/Concern

- Power Lift Gate (PLG) operation. (see M-Tips)
 - Reset procedure after battery drain.
 - PLG height adjustment programming.
- 2nd row seat USB ports charging operation. (if equipped)
- Interior seat and upholstery condition.
 - Staining and marking to the seats or the interior upholstery.
 - Visible seat foam through the seams.
 - Loose or disconnected seat fabric.
 - Excessive wrinkling or deformation in the seat leather or fabric.
- Other appearance issues with trim or seals.
 - Door seals bent or kinked.
 - Window run channel(s) correctly installed.
- Audio system operation. (MAZDACONNECT now added)
- Excessive rattle or squeak noises while test driving.
 - Center console, center stack/shifter area.
 - Door panel(s)
- Seat heater operation.