



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Radio HVAC IPC Blank Out When Operating A Snow Plow

**Models:** 2014 Chevrolet Silverado 1500  
2015-2016 Chevrolet Silverado  
2014 GMC Sierra 1500  
2015-2016 GMC Sierra  
With Snow Plow Prep Package (RPO VYU)

*This PI was superseded to update the Recommendations/Instructions. Please discard PIT5387B.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Some owners may experience any of the following: IPC cluster/radio/HVAC display blanks out, Bluetooth phone or Pandora connection dropped, the radio station or volume changes when operating the snow plow.

A snow plow places very high electrical loads on a truck's charging system when it is being operated (during plow movement). It demands the highest load (as high as 200 amps) when it is raised up completely or turned to either left or right maximum angle. As this load is turned on and off, the truck's charging system has to react within a fraction of a second to either increase or decrease its output to meet the plow's requirements.

There is no way for the truck's charging system to know when the driver is going to operate the snow plow, and in some cases, when the load is suddenly turned off, the charging system may momentarily over-charge for a fraction of a second. If this happens it can cause the various complaints listed above.

### Recommendation/Instructions

GM Engineering has released a generator snow plow jumper harness, part number 84043394, to correct this concern. Please reference the latest version of GM Upfitter Integration Bulletin 124 for additional information and installation instructions. To view this bulletin, access <http://www.gmupfitter.com/>, select the "TECHNICAL BULLETINS" tab followed by "Show all bulletins".

### Parts Information

Part Number	Description	Qty
84043394	Generator Snow Plow Jumper Harness	1

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
0580178*	Install Generator/Snow Plow Harness	1.2 hr

\* This is a unique labor operation for bulletin use only.

## ADDITIONAL SI KEYWORDS:

15208

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION