## TECHNICAL BULLETIN LTB00841NAS3 05 APR 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

This reissue replaces all previous versions. Please destroy all previous versions.

#### **SECTION: 417-01**

Halogen Headlamp Bulbs

### AFFECTED VEHICLE RANGE:

LR2 (LF)

Model Year: 2008-2015
VIN: 000212-439912
Assembly
Plant: Halewood

Range Rover Evoque (LV)

Model Year: 2012-2016

VIN: 000447-084000

Assembly Halewood

#### **MARKETS:**

NAS

#### **CONDITION SUMMARY:**

Situation: On vehicles fitted with halogen headlamps, the HB3 halogen bulbs may have blown at low time in service.

Cause: This may lead to earlier than expected bulb replacement.

Action: Should a customer express this concern, follow the Service Instruction below.

**PARTS:** 

LR081691 Resistive cable wire Quantity: 2

Cable tie (locally sourced) 100 x 2.5mm Quantity: 2

#### TOOLS:

No Tools Required

#### **WARRANTY:**

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

| DESCRIPTION  | SRO      | TIME<br>(HOURS) | CONDITION<br>CODE | CAUSAL PART |
|--|----------|-----------------|-------------------|-------------|
| Remove for access - Both headlamps - LR2 (L359)                | 86.40.54 | 0.1             | 46                | LR058361    |
| Install Resistive cable wire - LR2 (L359)                      | 05.10.10 | 0.1             | 46                | LR058361    |
| Remove for access - Both headlamps - Range Rover Evoque (L538) | 86.40.54 | 1.0             | 46                | LR058361    |
| Install Resistive cable wire - Range Rover Evoque (L538)       | 05.10.10 | 0.1             | 46                | LR024261    |

NOTE: Normal Warranty procedures apply.


#### SERVICE INSTRUCTION:

NOTE: the resistive wire MUST be fitted to BOTH headlamps BELOW the projector unit.

1. Remove the left-hand and right-hand headlamp assemblies (see TOPIx Workshop Manual, section 417-01: Exterior Lighting).


# 2. NOTE: left-hand headlamp shown; right-hand headlamp similar

Remove the left-hand headlamp bulb access cover.




E183422


3. Disconnect the HB3 connector from the bulb socket.



4. Release the existing wires from the locking clips.




5. Install in the resistive wire to the existing HB3 connector.



E183425


6. NOTE: the resistive wire MUST be fitted BELOW the projector

Install the resistive wire BELOW the projector unit.



E183426

7. Pass the resistive wire through the gap between the existing wiring and the body of the lamp.




E183427

8. NOTE: to prevent rattling, the connector must be installed as near as possible to the existing wire,




Using a suitable locally sourced cable tie, install the resistance wire to the http://topix.landrover.jlrext.com/topix/content/document/view?id=641990

existing wire.



9. Using a suitable tool, cut any excess from the cable tie.




E183429




Install the connector from the resistive wire to the bulb socket.

unit and not in contact with projector assembly.



11. Install the left-hand headlamp bulb access cover.

E183620



E183422

- 12. Repeat the procedure to the right-hand headlamp.
- 13. Install the left-hand and right-hand headlamp assemblies (see TOPIx Workshop Manual, section 417-01: Exterior Lighting).