



---

# SERVICE BULLETIN

---

Classification:

BT16-021

Reference:

NTB16-103

Date:

October 31, 2016

---

## 2014 – 2016 FRONTIER; MANUAL SEAT TRACK ADJUSTMENT DOES NOT LOCK INTO POSITION

**APPLIED VEHICLE:** 2014 – 2016 Frontier (D40) equipped with manual front seat

### IF YOU CONFIRM

The seat track latching pawls for a front seat (left or right) are not synchronized:

- The inboard track latches, but the outboard track does not latch unless the seat is pushed/pulled into position.

**NOTE:** The customer may report the following if this issue should occur:

- The seat track seems loose when braking or accelerating.
- The seat track is difficult to lock in place.
- After adjusting the seat track, it shifts/locks into place while driving.

### ACTION

Adjust/synchronize the outboard seat track per the Service Procedure in this bulletin.

**IMPORTANT:** The purpose of ACTION (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

## SERVICE PROCEDURE

**NOTE:** The driver seat is shown in Figures 1 - 3; the passenger seat is similar.

1. Remove the leg cover from the outboard seat track.



Figure 1

2. Loosen, don't remove, the outboard seat track mounting bolts.




Figure 2

3. Adjust the seat and outboard track as needed to ensure track adjustment pawls are synchronized (they lock at the same time on both sides):
  - Tap the outboard seat track forward or backward as needed.
  - By hand, move the seat cushion as needed.



Figure 3

4. Once the seat tracks are synchronized, tighten the seat track mounting bolts.
  - Torque bolts to: 45 N•m (4.6 kg-m, **33 ft-lb**)
5. Re-install the leg cover.

### CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Adjust Manual Seat Track- One or Both	(1)	VX4TAA	ZE	32	0.2

(1) Refer to the electronic parts catalog (FAST or equivalent) and use the appropriate Seat Adjuster Assembly part number (87450-\*\*\*\*\*) as the primary failed part.