



GROUP
Body Electrical

MODEL
2015-2017MY Soul EV (PS EV)
2016-2017MY K900 (KH)
2017MY Optima Plug-in Hybrid (PHEV)

NUMBER
PS353 (Rev 1
December 2016)

DATE
October 2014



TECHNICAL OPERATIONS

SUBJECT: NAVIGATION HEAD UNIT REPLACEMENT

This article provides information regarding navigation head unit replacement on 2015 - 2017MY Soul EV (PS EV), 2016 - 2017MY K900 (KH), and 2017MY Optima Plug-in Hybrid (PHEV). It is important to note that the head units in these vehicles contain a modem and should NOT be swapped between vehicles under any circumstances. Swapping a head unit from one vehicle to another may result in a non-operational UVO eServices on one of the vehicles. If a head unit needs to be replaced, the factory recommendation is to always order a replacement head unit to ensure proper eServices operations using the new installed/replaced head unit.

Follow the instructions below to determine additional steps that a customer may need to perform for the eServices to be operational after a head unit replacement.



After installation of the replacement head unit:

Model	Action
2015-2016MY Soul EV	Customer will need to perform the in-vehicle eServices enrollment again.
2017 MY and beyond Soul EV	Customer will not have to perform the in-vehicle enrollment since the modem should automatically sync up to the previous modem's status.
2016MY and beyond K900 KH	Customer will not have to perform the in-vehicle enrollment since the modem should automatically sync up to the previous modem's status.
2017MY and beyond Optima PHEV	Customer will not have to perform the in-vehicle enrollment since the modem should automatically sync up to the previous modem's status.