VOLVO CAR SERVICE AND PARTS BUSINESS



Technical Journal

TITLE:							
Rear door, water intrusion							
REF NO:	ISSUING DEPARTMENT:	CAR MARKET:					
TJ 31542	Technical Service	United States and Canada					
	PARTNER:	ISSUE DATE:	STATUS DATE:				
3 US 7	7510 Volvo Car USA	2016-05-13	2016-05-17				
FUNC GROUP:	FUNC DESC:						
8400	Outside trim parts, glass, sealing mould	Page 1 of 7					

"Right first time in Time"

Attachment

File Name	File Size
TJ 31542.pdf	1.0954 MB

Vehicle Type

Туре	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256						2016-9999		0000561-9999999	201605-999952

CSC Customer Symptom Codes

Code	Description
R2	Doors/Water leakage/Rear side door

VST Operation Number

VST Operation Number	Description	
98630-2	Scraper moulding side door adjust acc. to TJ31542	

DTC Diagnostic Trouble Codes



Text

DESCRIPTION:

Water may accumulate on the rear door sill. Water may come out of the lower edge of the rear doors when opening the rear doors.

SERVICE:

Please follow attached service instructions.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8400.

To view TJ attachment continue to next page. This TJ has one attachment.


VOLVO	olvo Car Customer Service	TJ 31	1542
Title	Weatherstrip, door window, rear	Page	1 (5)
Action	Adjustment	Operation number:	98630-2

Affected vehicles

Г


Model year	Model	
2016	XC90	(16-)

Color symbols



Note! This colour chart displays (in colour print and electronic version) the importance of the different colours used in the images of the method steps.


- 1. Used for focused component, the component with which you will do something.
- 2. Used as extra colors when you need to show or differentiate additional parts.
- 3 . Used for attachments that are to be removed/installed. May be screws, clips, connectors, etc.
- 4 . Used when the component is not fully removed from the vehicle but only hung to the side.
- 5 . Used for standard tools and special tools.
- 6 . Used as background color for vehicle components.





TJ 31542	Page 3 (5)
Removal	
	Caution! Make sure that the component is not bent. Remove the marked part. On both sides.
Installation	
	Make sure to replace the marked component with a new.
31402039 X2	

TJ 31542

Page 4 (5)







Cut following the dotted lines.

