



Service Bulletin

TECHNICAL

Subject: Steering Wheel Oscillation Between 5-53 MPH (8-85 KM/H)

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2016	2016	SOP	July 15, 2015	All	All
GMC	Canyon	2016	2016	SOP	July 15, 2015	All	All

Involved Region or Country	North America
Condition	Some customers may comment on a steering wheel oscillation between 5-53 MPH (8-85 KM/H). This typically occurs after driving over potholes or rough roads.
Cause	This may be due to an internal condition within the steering gear.

Correction

If you encounter a vehicle with the above concern, replace the steering gear assembly. Refer to *Electric Belt Drive Rack and Pinion Steering Gear Replacement* in SI.

Parts Information

Description	Part Number	Usage
GEAR ASM-ELEC BELT DRIVE R/PINION STRG	23353847	Short Wheel Base LCV Short Wheel Base LFX (2WD Only)
GEAR ASM-ELEC BELT DRIVE R/PINION STRG	23353848	Short & Long Wheel Base LWN Long Wheel Base LFX

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
7421770	Electric Belt Drive Rack and Pinion Steering Gear Replacement	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION