

# **Service Bulletin**

## TECHNICAL

#### Subject: Park Assist Sensor Blocked Message Displayed

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Volt	2016	2016			All	All

Condition	Some customers may comment on a "Park Assist Sensor Blocked" message displayed.
Cause	This may be caused by tape installed by the plant covering the sensors during the initial learn process.

#### Correction

Important: Do not replace the sensors for this condition.

If you encounter a vehicle with the above concern, complete the following steps:

- 1. Vehicle should be room temperature.
- 2. Make sure all sensors are clean and clear of any obstructions within 50 cm.
- 3. In GDS2 go to Parking Assist Control Module section then Configuration / Reset Function perform "Parking Assist Sensor Learn."
- 4. Drive and maintain a vehicle speed over 25 mph (40 km/h) for 1 minute.
- 5. After completion of learn, cycle ignition allowing module to go to sleep.
- 6. Verify system operation and sensors are working correctly and no DTCs are set.

### Warranty Information

Labor Operation	Description	Labor Time		
6480278*	Re-Learn Park Assist Sensors Using GDS	0.4 hr		
*This is a unique Labor Operation for Bulletin use only.				

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION