



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Engineering Information – Intermittent HVAC Cooling Issues During Driving

**Models:** 2016 Chevrolet Silverado, Suburban  
2016 GMC Sierra, Yukon  
Equipped with HVAC System (RPO C60, CJ2, CJ3 or CJ4)

**Attention:** Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

### Condition

**Important:** If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI.

Some customers may comment that while driving the vehicles HVAC cooling intermittently blows warm.

**Note:** This may not be able to be duplicated when brought into service.

### Cause

GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

### Instructions

If you encounter a vehicle with the above concern, complete the following steps:

1. Confirm that the A/C system has proper charge.
2. Correct and clear any DTCs that may be present.
3. If the condition is still not corrected, contact the engineer listed below.

### Contact Information

Engineer Name	Phone Number
James Resutek	586-859-9509

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

## Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
4480438*	Engineering Information – Intermittent HVAC Cooling Issues During Driving	0.5 hr
*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.		

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION