



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Clunk Or Rattle Noise From Steering Over Bumps

**Models:** 2015 - 2016 Chevrolet Colorado  
2015 - 2016 GMC Canyon

*PI superseded to update Models and Recommendations section. Please discard copies of PIT5489.*

### Condition/Concern

The customer may state there is a rattle or clunk noise from the front of vehicle over bumps. The technician may isolate this noise to the lower steering intermediate shaft.

### Recommendation/Instructions

Engineering has released a redesigned lower intermediate shaft for this noise concern. Replace the lower intermediate shaft with the part number listed below.

### Parts Information

Part Number	Description	Qty
84039333	Lower Intermediate Shaft	1

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
7441980	Replace Intermediate Shaft	Use Published Labor Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION