



**Countries:** CANADA, UNITED STATES, MEXICO **Document ID:** IK1600222  
**Availability:** ISIS, FleetISIS **Revision:** 1  
**Major System:** CAB / SLEEPER / HOOD **Created:** 6/21/2016  
**Current Language:** English **Last Modified:** 6/21/2016  
**Other Languages:** NONE **Author:** David Smith  
**Viewed:** 151

[Less Info](#)

Hide Details

Coding Information

<b>Copy Link</b> 	<b>Copy Relative Link</b> 	<b>Bookmark</b>  <a href="#">View My Bookmarks</a>	<b>Add to Favorites</b> 	<b>Print</b> 	<b>Edit Document</b> 	<b>Provide Feedback</b> 	<b>Helpful</b>  2	<b>Not Helpful</b>  1
----------------------	-------------------------------	--	-----------------------------	------------------	--------------------------	-----------------------------	-------------------------	-----------------------------

**Title:** Power Window Binding

**Applies To:** ProStar, WorkStar, TranStar, DuraStar, TerraStar

## CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

06/21/2016 - Initial Article Release, and addressed feedback

## DESCRIPTION

This document will guide the user through initial diagnostic steps for window binding.

## SYMPTOM(s)

**Customer states the window binds, or gets stuck when rolling up.**

DTC/Light	Description
N/A	

**Customer Observations or Concerns:**

Window rolls up slowly  
 Window gets stuck when used  
 Window is binding

## SPECIAL TOOL(s) / SOFTWARE

Tool Description	Tool Number	Comments	Instructions
N/A			

[Tools Resource Center](#)

## SERVICE PARTS INFORMATION

Kit Description	Part Number	Quantity Required	Notes
Seal, Door Glass Run Channel Front	3588772C1	1 (per side)	Part works on either side of the vehicle.

**DIAGNOSTIC STEP(s)**

Step	Action	Decision
1	<b>DIAGNOSTIC:</b> Perform visual inspection of the window tract experiencing the issue (See Figure 1 & 2)	<b>Yes.</b> Adjust window channel track to reflect proper alignment as shown in figure 1, and retest. If issue still persists go to Step 2.
		<b>No.</b> Go to Step 2

Step	Action	Decision
2	<b>DIAGNOSTIC:</b> Does the window continue to bind?  Note : If window track does not repair the concern, go ahead and continue window regulator/track diagnostics	<b>Yes.</b> Replace with window channel track with P/N : 3588772C1
		<b>No.</b> Release the vehicle.

**Appendix :**



**Figure # 1 : Window Track Alignment**



Figure # 2 : Window Track Alignment

### **REPAIR STEP(s)**

For repair steps go to Vehicle Service Manual that is experiencing the issue.

### **WARRANTY INFORMATION**

Warranty Claim Coding:

<b>Group:</b>	16012 - Side Doors
<b>Noun:</b>	071 - Channel, Glass Run

Standard Repair Time(s):

Step	Repair	Model	Engine	SRT
1-3	Cab Door Glass Run Channels and/or Seals	All	N/A	For SRT Times and Elemental Steps <a href="#">Click Here</a>

- Link to the Standard Repair Time Manual: [Click Here](#)

Claim SRT Example:

Claim Comment Suggestion:

Special Requirement(s):

### **OTHER RESOURCES**

[Master Service Information Site](#)

Viewed: 150

Helpful: 2

Not Helpful: 1

Staff ID	Client ID	Comments	Created Date
	DY38357	You received the following feedback From: dy38357 - Jezreel Bohlander Email Address: jbohlander@mctrux.com Job Classification: AD006, Warranty Manager Dealer: MCCANDLESS TRK CENTER Feedback: The article is not allowing the figures to be downloaded on any of our dealership computers. Can I get pictures of the figures that are supposed to accompany this article?	6/22/2016 8:13:42 AM
	DY09801	You received the following feedback From: dy09801 - Mike Kanoski Email Address: KanoskiM@RushEnterprises.com Job Classification: SE008, Service Technician Dealer: RUSH TRK CTR OF S OH Feedback: cannot view picture. I tried on several laptops	6/29/2016 7:45:45 AM

Copyright © 2016 Navistar, Inc.