Reference	SSM73053
Models	Discovery Sport / L550
	Range Rover Evoque / L538
Title	17 MY- Cannot Activate WIFI Card (PSIM) at PDI
Category	Electrical
Last modified	10-Nov-2016 00:00:00
Symptom	207000 Entertainment Systems
Attachments	PSIM Images.pdf (PSIM Images.pdf)
Content	leeua

Content

Issue

The WIFI SIM Card cannot be activated at PDI on a select number of VIN's - see below.

Cause

Incorrect ICC number (Ref image 1) entered into the database at Halewood.

Action

See VIN's below and if applicable, update the PSIM as follows:

PSIM Update to be carried out by the Retailer.

NOTE: This must be completed before a vehicle is associated to a user on InControl.

- 1. Get the PSIM from the Vehicle and note the ICCID number (19/20 digits) This is located on the outside of the packaging and is marked as ICCID. (See Image 1).
- 2. Log into the InControl Retailer Admin Portal.
- 3. Search for the VIN.
- 4. Check no customer associated.
- 5. Click on Manage (Image 2).
- 6. Enter the new ICCID (NOTE: Although it says to replace, you are replacing a blank ICCID with a new one).
- 7. Click Submit to validate (Image 3).
- 8. There is a pop up reminder to fit the PSIM into the vehicle. Please click OK (Image 4).
- 9. Final screen confirms successful update. The vehicle may now be associated with an InControl account and the customer may accept Terms and Conditions. This will result in the standard Trial activation being completed (Image 5).

List of Affected Vins

SALVP2BG3HH175565

SALVP2BG1HH190002 SALVP2BGXHH181430 SALVR2BG8HH188693 SALVP2BG1HH182837 SALVR2BG7HH188667 SALVP2BG5HH190066 SALVP2BG1HH191053 SALCR2BGXHH651358

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

- 1 = Poor Basic information provided The SSM does not help me resolve the customer concern.
- 3 = Average Adequate information provided The SSM partially helps me resolve the customer concern.
- 5 = Excellent All required information provided to resolve the customer concern.